

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TPHSBC -
Xiao Chen,

Vehicle No PC1366H

TOYOTA HIACE COMMUTER

KDH2220035418

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	FRONT BUMPER <i>Dislnd</i>	<i>1480.80</i> <i>1110.67</i>	594.30	✓
2	FRONT BUMPER SIDE HOLDER <i>2nd</i>		95.20	✓
3	HEADLAMP <i>lt</i>		791.40	✓
4	FRONT DOOR <i>Repair</i>		1574.20	X
5	FRONT STEP GARNISH <i>xbr m</i>		191.20	X
<u>SPECIAL NETT ITEMS</u>				
1	FRC NT BUMPER CLIPS <i>mm</i>	<i>30</i>	30.00	✓
Total Parts			30.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
<u>LABOUR</u>			
1	PANEL BEATING	500.00	<i>300</i>
2	SPRAY PAINTING	600.00	<i>400</i>
3	WIRING	50.00	<i>30</i>
4	TO APPLY TUFF COAT	100.00	<i>30</i>
5	TO TRANSFER DOOR FITTINGS	150.00	<i>X</i>
Labour Total :		1400.00	<i>760</i>
TOTAL (PARTS & LABOUR):		6565.43	

Total: 1900.67

4/3 1.5K.

03Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: