



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 3883Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	108.50	108.50
1	REAR TAIL GATE	DENTED	1,485.00	1,485.00
1	EVERY - STICKER	NECESSARY	49.80	49.80
1	LOGO - EMBLEM	NECESSARY	38.80	38.80
1	TAIL GATE OUTER HANDLE	DAMAGED	85.80	85.80
1	TAIL GATE INNER BOARD	NOT NECESSARY	298.00	-
1	REAR WEATHERSTRIP	CUT	139.80	139.80
1	REAR BUMPER	DEFORMED	796.00	796.00
1	REAR PANEL	DENTED	408.00	408.00
1	REAR TAIL GATE LOCK	DAMAGED	132.00	132.00
2	REAR BUMPER LAMP @\$68.80	CRACKED	137.60	137.60
1	STAY PANEL LOCK SCREW CARRIAGE	NOT NECESSARY	48.90	-
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	425.80	-
	LESS 15% DISCOUNT		-	-507.20
			4,154.00	2,874.10
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR NUMBER PLATE (SN)	CRACKED	35.00	35.00
1	SET BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	STICKER - 5PAX & 70KM (SN)	NECESSARY	30.00	30.00
1	REAR CAMERA (SN)	NOT NECESSARY	500.00	-
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			935.00	355.00
<u>LABOUR</u>				
	TO KNOCK & CHANGE PARTS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE.		800.00	700.00
	REMOVE & REFIX REAR WINDSCREEN GLASS.		150.00	120.00
	SPRAY REAR AFFECTED PARTS.		800.00	700.00
	END PANEL SEALANT.		80.00	60.00
	TO REMOVE AND REFIX EXHAUST SYSTEM.	NOT NECESSARY	120.00	-

Report Ref No. CS/AGI23001153/Acy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WIRING CHECKS.		50.00	30.00
	TO REMOVE REVERSE SENSOR AND REAR CAMERA.		150.00	100.00
			2,150.00	1,710.00
GRAND TOTAL			7,239.00	4,939.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS/AGI23001153/Acy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.