

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0032/2023
DATE : 01-FEB-2023

EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD

#17-00 TOWER BLOCK

MND COMPLEX S(069110)

TEL : 62239433

FAX : 62234190

ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR WU XIANGYU
ADDRESS : 19 SHELFORD ROAD
#09-08
S(288408)
TELEPHONE NO : 84266879/96678337

LICK

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBA4556H
VEHICLE NO : SMS3871D
MODEL CODE : BDTARCZB17EWA----K19
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019
ENGINE NO : HR16950696C
CHASSIS NO : MNTBBAB17Z0037204
MILEAGE : 1 KM
DATE IN : 01/02/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 30/01/2023

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMS3871D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RCI	R/INSTALL OR RENEW REVERSE CAMERA ASSIT TO REPAIR	120.00	X
2 RISC	REMOVE/INSTALL SEAT & CUSHION CARPET	240.00	120 X
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR 3X AFFECTED PANEL	360.00	120
4 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
5 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	/
6 ZZ/001	REPAIR RH/LH RR FENDER & RR FLOOR PANEL RENEW RR BUMPER,END PANEL & TRUNKLID	1560.00	1170
7 ZZ/002	S/PAINT RH/LH RR FENDER,RR END PANEL,RR BUMPER, TRUNKLID,RR FLOOR PANEL	1600.00	750
8 ZZ/003	TRANSFER MECHANISM PART FOR TRUNKLID	60.00	/
9 ZZ/004	CHECK RR LIGHTING	48.00	/
TOTAL LABOUR CHARGES		4243.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMS3871D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	HINGE TRUNK(\$44.2X2) X	H4400-3RAMA	88.40		
2	FINISHER ASSY CA	84810-3ST1A	199.40		
3	COMB LAMP RR ?	26555-3SN5E	250.00		
4	COMB LAMP ?	26550-3SN3E	250.00		
5	ABSORBER ENERGY ?	85090-3SN5A	205.00		
6	COMB LAMP ?	26555-3SN0D	375.00		
7	COMB LAMP ?	26550-3SN0D	375.00		
8	ORNAMENT ASSY R X	26560-5C000	66.90		
9	ORNAMENT ASSY L X	26565-5C000	66.90		
10	R/LAMP CLIP(\$5.3X4) m	26557-2U000	21.20		
11	CLIP(\$1.4X10) m	01553-10501	14.00		
12	CLIP(\$1.5X10) m	01553-09321	15.00		
13	CROMMET(\$2.9X2) m	63846-5V000	5.80		
14	LOCK ASSY-TRUNK ?	84630-3AW0A	76.50		
15	W/STRIP T/LID X	84830-3SB3J	94.90		
16	EMBLEM m	84890-3RA0B	54.50		
17	EMBLEM m	84890-3RA1B	102.90		
18	CARPET-LUGGAGE ?	84902-3SB0A	493.90		
19	PLATE-LUGGAGE ?	84921-3SB0A	106.00		
20	SPACER ?	84978-3SB0A	184.10		
21	FASCIA BUMPER de-	85022-3SN5H	773.00		
22	TRUNK LID bt	H430M-3SBMA	722.80		
23	PANEL-REAR UPPE ngr	G9110-3SBMA	475.90		
24	BRETT RE BUMPER ?	85227-3SN5A	18.00		
25	BRETT BUMPER ?	85226-3SN5A	18.00		

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMS3871D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	STAY RR BMPR ?	85213-EE530	49.10		
27	STAY RR BMPR ?	85212-EE530	52.10		
28	REAR LICENCE PLATE ?	RLP			60.00
29	SUNDRIES <i>m</i>	NPN			30.00 <i>20</i>
30	REVERSE SENSOR ?	SENSOR-XP380N			144.85
SUB TOTAL			5154.30	0.00	234.85
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1030.86	0.00	0.00
GRAND TOTAL			4123.44	0.00	234.85
OVERALL TOTAL			4358.29		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMS3871D

TOTAL LABOUR CHARGES	4243.00
TOTAL SPARE PARTS CHARGES	4358.29
GRAND TOTAL	8601.29 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

: Rsm - 44 9000068
: 08/02/27 @ 1120
: 5 days
: 0.00
: 0.00
: Rezy Sebra mil

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: