

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CTI22002976/ETY3N2  
**Date:** 17/05/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00017002100
<b>Claimant Vehicle No :</b>	SMG3212U	<b>Insured Vehicle No :</b>	PC7914L
Date of Loss:	29/03/2022	Nature of Claim:	TP
		Claim No:	SNM22D202180/C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMG3212U</b>	Engine No:	LEB7101068
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP72000716
Reg. Date:	14/12/2018 (Man. Year: 2018)	Odometer:	330553 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	09/05/2022		
Date Inspected:	31/03/2022	Inspected At:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center Singapore 627605
Estimated Period of Repair:	7.0 days		

<b>Adjuster:</b>	CHEN TSUE YEE	<b>Manager:</b>	DENISE TAY KWEE CHENG
------------------	---------------	-----------------	-----------------------

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 May 2022)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>LKK Auto Consultants Pte Ltd/SMG3212U/17/05/2022 13:28</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

<b>LKK Auto Consultants Pte Ltd/SMG3212U/17/05/2022 13:28.</b> Not valid without Reference section.
-----------------------------------------------------------------------------------------------------

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SMG3212U/17/05/2022 13:28. Not valid without Reference section.
----------------------------------------------------------------------------------------------

< END OF ESTIMATES >