



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 9372G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	BUCKLED	1,232.00	1,232.00
1	REAR BOOT LID EMBLEM 'MERCEDES' LOGO	NECESSARY	38.00	38.00
1	REAR BOOT LID EMBLEM 'C180'	NECESSARY	59.00	59.00
1	REAR BOOT LID OUTER CHROME MOULDING	REUSE	144.00	-
2	REAR BOOT LID NUMBER PLATE LAMP RH/LH	RE-USE	30.00	-
1	REAR BOOT LID INNER LOCK	NOT NECESSARY	212.00	-
1	REAR BOOT WEATHERSTRIP	DAMAGED	132.00	132.00
2	REAR TAIL LAMP RH/LH	CRACKED	898.00	440.00
1	REAR BUMPER	CRACKED	1,125.00	1,125.00
2	REAR BUMPER CHROME MOULDING RH/LH	NECESSARY	164.00	164.00
1	REAR BUMPER CHROME MOULDING CENTRE	DAMAGED	89.00	89.00
2	REAR BUMPER BRACKET RH/LH	BENT	60.00	60.00
1	REAR BUMPER RETAINER CENTRE	BENT	115.00	115.00
2	REAR BUMPER SIDE RETAINER RH/LH	NECESSARY	56.00	25.00
1	REAR BUMPER REINFORCEMENT	BENT	523.00	523.00
2	REAR FENDER DRAIN GARNISH RH/LH	NOT NECESSARY	270.00	-
2	SET REAR FENDER DRAIN GARNISH CLIP RH/LH	NOT NECESSARY	102.00	-
1	REAR FENDER AIR VENT RH	BUCKLED	38.00	25.00
1	REAR END PANEL	BENT	891.00	891.00
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	95.00	-
1	SET REAR END PANEL INNER GARNISH CLIP	NECESSARY	21.00	21.00
	LESS 10% DISCOUNT		-	-493.90
			6,294.00	4,445.10
	<u>SPECIAL NETT ITEMS</u>			
4	REVERSE SENSOR (SN)	SHORT CIRCUIT	550.00	250.00
			550.00	250.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING REAR FENDER RH/LH, REAR BOOT FLOOR PANEL AND REAR FRAME MEMBERS. TO CUT/WELD REAR END PANEL. TO REMOVE AND REFIT ABOVE PARTS.		2,000.00	700.00

Report Ref No. CS3/LPC22009013/Rny3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,800.00	800.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO RUST PROOF AFFECTED AREAS.		90.00	60.00
			3,970.00	1,590.00
GRAND TOTAL			10,814.00	6,285.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CS3/LPC22009013/Rny3m4-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.