



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | | | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|-----------------|----------------------------------------------------------------------------------------------|------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | CS3/LPC22009013/Rny3-1 | |
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | | Ref: CS3/LPC22009013/Rny3 Date: 13/09/2022 03/02/2023 Code: LPC2 | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| Insured Veh. | GBG 2863C | Veh. Inspected | SKA 9372G | | |
| Policy No. | | Coverage (\$) | 0.00 | | |
| Claim No. | 22/22/22/NC05/026285 | Excess (\$) | 0.00 | | |
| Assign From | GERALD POH | Assign Date | 13/09/2022 03/02/2023 | | |
| 2. Vehicle Particulars & Condition | | | | | |
| Make & Model | | c.c | 0 | | |
| Engine No. | HIDDEN | Year of Reg. | | | |
| Chassis No. | | Colour | | | |
| Odometer | - | Steering | | | |
| Brakes | | Modification | | | |
| General | | | | | |
| 3. Conditions of Tyres | | | | | |
| | Size | Make | Balance | | |
| R/H Front Tyre | | | mm | | |
| L/H Front Tyre | | | mm | | |
| R/H Rear Tyre | | | mm | | |
| L/H Rear Tyre | | | mm | | |
| 4. Description of Damages | | | | | |
| | | | | | |
| 5. General Information | | | | | |
| Accident Date | 12/09/2022 | Inspection Date | 14/09/2022 | | |
| Survey held at | HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722 | | | | |
| 5a. Remarks | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | |