



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 3865B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	BUCKLED /CUT	1,800.00	1,360.40
10	FRONT BUMPER CLIPS @\$5.00 (CONSISTENT)	NECESSARY	50.00	50.00
1	HEADLAMP LH (CONSISTENT)	SERVICEABLE	3,400.00	-
1	FRONT RADIATOR GRILE BASE (CONSISTENT)	SERVICEABLE	150.00	-
1	FRONT RADIATOR GRILE CHROME (CONSISTENT)	SERVICEABLE	680.00	-
	LESS 10% DISCOUNT		-	-141.04
			6,080.00	1,269.36
	<u>LABOUR</u>			
	SPRAY PAINTING FRONT BUMPER INCLUDING BLENDING.		300.00	220.00
	REPLACE ,REPAIR AND REFIT ACCIDENT AFFECTED AREAS.		300.00	200.00
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.	NOT NECESSARY	100.00	-
	OBD DIAGNOSIS AND RECTIFY FAULT CODES.	NOT NECESSARY	150.00	-
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	15.00
			880.00	435.00
	GRAND TOTAL		6,960.00	1,704.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,350.00

Report Ref No. CC4/HSB23001168/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.