

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB23001173/KPA3Q2**Date:** 20/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SLX6599G**Insured Vehicle No :** SLM4222P

Date of Loss: 31/12/2022

Nature of Claim: TP

Claim No: MFL2023D0004561

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLX6599G**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB6545752

Reg. Date: 04/04/2018 (Man. Year: 2017)

Chassis No: GP71204604

Colour: Metallic Pearl White

Odometer: 204370 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Farroad 4 mm

Rear Left Side: Firenza 3 mm

Front Right Side: Farroad 4 mm

Rear Right Side: Firenza 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,322.00	854.00	468.00	35.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	845.00	725.00	46.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,892.00	1,699.00	1,193.00	41.25
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	2,892.00	1,350.00	1,542.00	53.32
+ GST 8.00/8.00% (S\$)	231.36	108.00	123.36	53.32
Nett Amount (S\$)	3,123.36	1,458.00	1,665.36	53.32
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		1,664.75		

INSPECTION

Date of Assignment: 31/01/2023

Date Inspected: 02/02/2023 Inspected At:

Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 May 2023)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX6599G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (WCP)	Bent	600.00 F	*600.00 F
2	1		*REAR TAILGATE SHUTTLE EMBLEM (WCP)	Necessary	50.00 F	*50.00 F
3	1		*REAR TAILGATE HYBRID EMBLEM (WCP)	Necessary	50.00 F	*50.00 F
4	1		*REAR TAILGATE WEATHERSTRIP (WCP)	Serviceable	80.00 F	*- F
5	1		*REAR WINDSCREEN MOULDING (WCP)	Necessary	40.00 F	*40.00 F
6	1		*REAR BUMPER (NPA)	Repair	0.00 F	*- F
7	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
8	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
9	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS
						F=Franchise part. S=SpcNett.
					Sub Total (S\$)	1,240.00 780.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	82.00 74.00
					Total Parts (S\$)	1,322.00 854.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	500.00	250.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER & ETC	New	500.00	400.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	0.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	15.00
Gross Labour Cost (S\$)			1,570.00	845.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >