

Vehicle Damage Assessment Report for [SLX6599G]

Estimate Created: 04/02/2023 12:58 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 15/05/2023 15:31 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Shuttle
Engine Type			
License Plate Number	SLX6599G	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$1,350.00 WITH 3 WORKING
DAYS

Insurlogic 4 (15/05/2023 15:30)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR TAILGATE (WCP)		1	600.00	10.00 %	660.00
REAR TAILGATE SHUTTLE EMBLEM (WCP)		1	50.00	10.00 %	55.00
REAR TAILGATE HYBRID EMBLEM (WCP)		1	50.00	10.00 %	55.00
REAR WINDSCREEN MOULDING (WCP)		1	40.00	10.00 %	44.00
Parts Subtotal					814.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR WINDSCREEN SEALANT		1.0	40.00	0.00 %	40.00
Materials Subtotal					40.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	250.00	0.00 %	250.00
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC	RnR	120.00	0.00 %	120.00
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	RnR	60.00	0.00 %	60.00
TO CHECK WIRING & ELECTRICAL SYSTEM	RnR	15.00	0.00 %	15.00

Paint

Paint					
Description		Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING		Full spray	400.00	0.00 %	400.00
Labor Rate	S\$ 50 / Hour			General Labor Subtotal	445.00
				Paint Labor Subtotal	400.00
				Labor Subtotal	845.00

Summary

Repair Cost	1,699.00
Discount(20 %)	(339.80)
	1,359.20
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	1,359.20