

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23001177/KPA3Q2**Date:** 25/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747_02
Claimant Vehicle No : SDD6151P **Insured Vehicle No :** SMN9723K
 Date of Loss: 26/01/2023 Nature of Claim: TP Claim No: MFL2023D0001291

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDD6151P**
 Make & Model: MAZDA 8 5-DOOR WAGON, 2.3 L SP.5EAT (A) Engine No: L310562037
 Reg. Date: 28/12/2015 (Man. Year: 2015) Chassis No: JM6LY1033G0301495
 Colour: Metallic Red Odometer: 126540 km
 Engine Capacity: 2261 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R15 Rear Tyre Size: 215/65 R15
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,305.72	3,517.36	8,788.36	71.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,330.00	1,670.00	55.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,305.72	4,847.36	10,458.36	68.33
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	15,305.72	3,800.00	11,505.72	75.17
+ GST 8.00/8.00% (S\$)	1,224.46	304.00	920.46	75.17
Nett Amount (S\$)	16,530.18	4,104.00	12,426.18	75.17
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		4,730.75		

INSPECTION

Date of Assignment: 02/02/2023
 Date Inspected: 03/02/2023 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)
 176 SIN MING DRIVE, #05-14
 Singapore 575721
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	M1-MPV	MAZDA 8 5-DOOR WAGON 2.3 L SP.5EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDD6151P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,937.00 FL	*1,562.80 FL
2	1		*TAILGATE LOCK	Repair	933.00 FL	*- FL
3	1		*TAILGATE LOCK SENSOR	Serviceable	320.00 FL	*- FL
4	1		*TAILGATE WEATHERSTRIP	Serviceable	421.00 FL	*- FL
5	1		*TIALGATE MAZDA LOGO	Necessary	99.70 FL	*42.80 FL
6	1		*TAILGATE 8 EMBLEM	Necessary	79.80 FL	*54.30 FL
7	1		*TAILGATE OUTER MOULDING CHROME GARNISH	Cracked	295.00 FL	*295.00 FL
8	1		*TAILGATE OUTER MOULDING	Cracked	566.00 FL	*566.00 FL
9	1		*REAR WINDSCREEN MOULDING	Necessary	194.00 FL	*194.00 FL
10	1		*TAILGATE INNER TRIM BOARD	Serviceable	899.90 FL	*- FL
11	1		*REAR BUMPER	Buckled	1,299.30 FL	*1,299.30 FL
12	2		*REAR BUMPER SIDE RETAINER	Serviceable	152.00 FL	*- FL
13	2		*REAR BUMPER BRACKET	Repair	136.00 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Repair	791.70 FL	*- FL
15	2		*REAR BUMPER TOW HOOK COVER	Serviceable	323.00 FL	*- FL
16	2		*TAILGATE LAMP	Serviceable	1,264.00 FL	*- FL
17	1		*TAILGATE INNER HANDLE	Serviceable	69.00 FL	*- FL
18	2		*TAILLAMP LOWER PANEL	Repair	1,170.00 FL	*- FL
19	2		*TAILLAMP	Serviceable	2,178.00 FL	*- FL
20	2		*TAILLAMP BRACKET	Serviceable	330.00 FL	*- FL
21	2		*REAR BUMPER SIDE REFLECTOR	Serviceable	530.00 FL	*- FL
22	16		*TAILGATE INNER TRIM CLIPS	Not Necessary	88.00 FS	*- FS
23	12		*REAR BUMPER CLIPS	Necessary	66.00 FS	*66.00 FS
24	2		*REVERSE SENSOR HOLDER	Serviceable	76.00 FS	*- FS
25	2		*REVERSE SENSOR (FACTORY ORIGINAL)	Shorted	560.00 FS	*200.00 FS
26	1		*TAILLAMP LOWER PANEL SEALANT	Not Necessary	100.00 FS	*- FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
28	1		*REAR LICENCE PLATE & FRAME	Serviceable	55.00 FS	*- FS
29	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					15,103.40	4,320.20
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,797.68	802.84
Total Parts (\$\$)					12,305.72	3,517.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,400.00	500.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNETC AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE, REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE, CHECK AND RE-ADJUST CLOSE GAP, ALIGNMENT AND WATER SEEPAGE	New	100.00	60.00
4	TO UNDER COAT ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	30.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	1,200.00	600.00
6	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK	New	150.00	120.00
Gross Labour Cost (\$\$)			3,000.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >