

ASS. REC. BY:

REF:

III / 23001177/Kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PDD 8151P Yr Regn: 12, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Mazda 8 C.C. 2261Colour: M. Red A/C: Insured / Std / NI / NASp. Reading: 126540 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6LY1033G0301495Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/85R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 26/1/23

Survey held at

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 EM not ready

10/2 11pm @ 3800 Cnh

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Not Authorized
11 Lp & 3800p
Delivery After Paint
4 days

Make/Model: MAZDA 8
Engine/Chassis No.: JM6LY1033G0301495
Date of accident: 26.01.23
Damaged area: Rear

Date: 06/02/2023
Claim Type: TP
VRN: SDD6151P



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate main <i>gate 1567.80</i>	<i>R</i> 1	\$ 1,937.00	\$ 1,937.00
2	Tailgate lock	<i>R</i> 1	\$ 933.00	\$ 933.00
3	Tailgate lock sensor	<i>sn</i> 1	\$ 320.00	\$ 320.00
4	Tailgate weatherstrip	<i>sn</i> 1	\$ 421.00	\$ 421.00
5	Tailgate 'MAZDA' logo <i>42.80</i>	<i>nu</i> 1	\$ 99.70	\$ 99.70
6	Tailgate '8' emblem <i>54.30</i>	<i>nu</i> 1	\$ 79.80	\$ 79.80
7	Tailgate outer moulding chrome garnish	<i>cm</i> 1	\$ 295.00	\$ 295.00
8	Tailgate outer moulding	<i>cm</i> 1	\$ 566.00	\$ 566.00
9	Rear windscreen moulding	<i>nu</i> 1	\$ 194.00	\$ 194.00
10	Tailgate inner trim board	<i>sn</i> 1	\$ 899.90	\$ 899.90
11	Rear bumper	<i>Bo</i> 1	\$ 1,299.30	\$ 1,299.30
12	Rear bumper side retainer	<i>sn</i> 2	\$ 76.00	\$ 152.00
13	Rear bumper bracket	<i>R</i> 2	\$ 68.00	\$ 136.00
14	Rear bumper reinforcement	<i>R</i> 1	\$ 791.70	\$ 791.70
15	Rear bumper tow hook cover	<i>sn</i> 2	\$ 161.50	\$ 323.00
16	Tailgate lamp	<i>sn</i> 2	\$ 632.00	\$ 1,264.00
17	Tailgate inner handle	<i>sn</i> 1	\$ 69.00	\$ 69.00
18	Taillamp lower panel	<i>R</i> 2	\$ 585.00	\$ 1,170.00
19	Taillamp	<i>sn</i> 2	\$ 1,089.00	\$ 2,178.00
20	Taillamp bracket	<i>sn</i> 2	\$ 165.00	\$ 330.00
21	Rear bumper side reflector	<i>sn</i> 2	\$ 265.00	\$ 530.00
Subtotal				\$ 13,988.40
List discount				20.00%
Total				\$ 11,190.72

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate inner trim clips <i>nu</i>	16	\$ 5.50	\$ 88.00
2	Rear bumper clips <i>nu</i>	12	\$ 5.50	\$ 66.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

3	Reverse sensor holder	Sm	2	\$ 38.00	\$ 76.00	X
4	Reverse sensor (Factory original)	Shot	2	\$ 280.00	\$ 560.00	2000m
5	Taillamp lower panel sealant	na	1	\$ 100.00	\$ 100.00	X
6	Rear windscreen sealant	Ma	1	\$ 120.00	\$ 120.00	400m
7	Rear licence plate & frame	Sm	1	\$ 55.00	\$ 55.00	X
8	Sundries	na	1	\$ 50.00	\$ 50.00	X
				Total	\$ 1,115.00	

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00	500d
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	20l
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	60l
4	To under coat all affected portions after repair.	0.5	\$ 100.00	30l
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00	120l
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00	600d
Total labour			\$ 3,000.00	

Estimate Grand Total	\$ 15,305.72
-----------------------------	---------------------

LK Auto Consultants hence holds the Repair of the following:
 • To respray damaged (dent) spray painting
 • To display damaged (dent) spray painting
 • Parts price are subject to confirmation
 • Third party survey is on a "With" condition basis
 • No illegal modification(s) is allowed
 • Supplementary items must be approved and
 is subject to final approval from LK Auto Consultants Company
 Authorised by Repairs
 Signature
 Date