

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB23001181/UPA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_02

**Claimant Vehicle No :** SMV8735R **Insured Vehicle No :** SLF5481M

Date of Loss: 20/01/2023 Nature of Claim: TP Claim No: MFL2023D0000987

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMV8735R**  
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NR5458160  
 Reg. Date: 26/10/2020 (Man. Year: 2020) Chassis No: MR2B23F3501211400  
 Colour: Blue Odometer: 70924 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm  
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,442.90	2,243.78	6,199.12	73.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,209.64	2,047.00	4,162.64	67.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,652.54</b>	<b>4,290.78</b>	<b>10,361.76</b>	<b>70.72</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>1,172.20</b>	<b>343.26</b>	<b>828.94</b>	<b>70.72</b>
<b>Nett Amount (S\$)</b>	<b>15,824.74</b>	<b>4,634.04</b>	<b>11,190.70</b>	<b>70.72</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 8.00% GST) (S\$)</b>		432.00		
<b>+ Doc/Search Fee (S\$)</b>		26.75		
<b>Nett Liability (S\$)</b>		<b>5,092.79</b>		

**INSPECTION**

Date of Assignment: 26/01/2023  
 Date Inspected: 07/02/2023 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)  
 2 Pandan Crescent  
 Singapore 128462  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMV8735R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE WITH CASING	Bent	68.00 FS	*68.00 FS
3	1		*SEALANT	Not Necessary	60.00 FS	*- FS
4	1		*HEADLAMP ASSY ,RH	Holder Cracked	1,547.20 FS	*1,083.04 FS
5	1		*HEADLAMP ASSY ,RH	Not Necessary	1,547.20 FS	*- FS
6	1		*GRILLE ,RADIATOR ,LW	Grazed	323.80 FS	*226.66 FS
7	1		*GRILLE ,RADIATOR LW	Cracked	109.30 FS	*76.51 FS
8	1		*COVER ,FR BUMPER ,L/	Deformed / Torn	592.80 FS	*414.96 FS
9	1		*PIECE ,RR BUMPER (4 PCS)	Necessary	19.60 FS	*34.30 FS
10	1		*RETAINER ,FR BUMPER	Not Necessary	120.70 FS	*- FS
11	1		*RETAINER ,FR BUMPER	Not Necessary	120.70 FS	*- FS
12	2		*CLIP	Not Necessary	6.00 FS	*- FS
13	2		*CLIP,PIN HOLD	Not Necessary	21.00 FS	*- FS
14	2		*RETAINER ,FR FENDER	Not Necessary	29.20 FS	*- FS
15	1		*REINFORCEMENT SUB-AS	Repair	480.20 FS	*- FS
16	1		*GRILLE RADIATOR OU	Cracked	85.20 FS	*59.64 FS
17	1		*MOULDING ,RADIATOR G	Not Necessary	47.30 FS	*- FS
18	1		*MOULDING ,RADIATOR G	Not Necessary	42.00 FS	*- FS
19	1		*GRILLE ,RADIATOR ,IN	Cracked	288.00 FS	*201.60 FS
20	1		*PROTECTOR ,RADIATOR	Not Necessary	23.70 FS	*- FS
21	1		*PROTECTOR ,RADIATOR	Not Necessary	17.60 FS	*- FS
22	1		*EMBLEM , SYMBOL	Scratched	70.10 FS	*49.07 FS
23	1		*HOOD SUB-ASSY	Repair	1,110.00 FS	*- FS
24	1		*SUPPORT SUB-ASSY HO	Repair	180.30 FS	*- FS
25	1		*SUPPORT ASSY ,RADIAT	Repair	1,173.80 FS	*- FS
26	1		*COVER ,RADIATOR	Not Necessary	329.20 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>8,442.90</b>	<b>2,243.78</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESET ECU AND REPROGRAMME	New	198.00	198.00
2	TO CHECK WIRING AND LIGHTING TO FOCUS HEADLAMP	New	134.64	72.00
3	TO REPLACE/REPAIR AIR FRONT ACCIDENT DAMAGE PARTS STRAIGHTEN /REALIGN ALL OTHER AFFECTED AREAS	New	3,168.00	792.00
4	TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS	New	2,624.00	900.00
5	PAINT REPAIR -SUPPLY MATERIALS	New	85.00	85.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,209.64</b>	<b>2,047.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >