

ASS. REC. BY:

REF:

AIG/23001189/Kcp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 1892

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Latitude

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

564483

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VFI AB 15AUC 282 712

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Firenze

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

31/1/23

D.O.I.

1/2/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S & Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/12 21:00 84400 max cab

Data/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Data/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD189Z*Not Authorized
L1Pny & 4400 Max***AAD2301-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

01 FEB 2023**SHD189Z**

VF1ABL15AUC282712

200303878K

RENAULT

LATITUDE

31/01/2023

SJK2915X/AIG

22/03/2016

PART

1 BUMPER COVER REAR
 1 BUMPER LOWER REAR
 1 BUMPER BRACKET CTR REAR
 1 BUMPER BRACKET SIDE RH REAR
 1 BUMPER RETAINER RH REAR
 1 BUMPER BRACKET SIDE LH REAR
 1 BUMPER RETAINER LH REAR
 1 ABSORBER REAR
 1 BUMPER BEAM REAR
 1 BUMPER BEAM BRACKET LH REAR
 1 BUMPER BEAM BRACKET RH REAR
 1 OUTER PANEL REAR (End Panel)
 1 OUTER PANEL REAR (End Panel)TRIM
 1 SPARE WHEEL PANEL
 1 SPARE WHEEL PANEL BRACKET LH
 1 SPARE WHEEL PANEL BRACKET RH
 1 FENDER PANEL REAR RH
 1 WHEELARCH REAR RH
 1 FENDER PANEL INNER TRIM REAR RH
 1 FENDER PANEL INNER REAR RH
 1 FENDER INNER BOARD RH
 1 SPARE TYRE BOARD
 1 TAILLAMP RH
 1 EXHAUST REAR
 1 EXHAUST BRACKET REAR
 1 EXHAUST CAP REAR
 1 BOOT REAR

LIST

\$ *B* 561.70 ✓
 \$ *R* 411.90 ✓
 \$ *Ln* 98.10 X
 \$ *Di* 82.10 ✓
 \$ *Di* 59.80 ✓
 \$ *Ln* 80.80 X
 \$ *Ln* 54.20 X
 \$ *Nsp* 217.30 X
 \$ *B* 547.80 ✓
 \$ *R* 114.50 X
 \$ *B* 114.50 ✓
 \$ *B* 745.80 ✓
 \$ *Ln* 404.56 X
 \$ *R* 1,229.40 X
 \$ *R* 70.60 X
 \$ *R* 69.20 X
 \$ *Bu* 1,933.20 ✓
 \$ *Ln* 275.40 X
 \$ *DePurn* 671.45 ✓
 \$ *R* 1,241.60 X
 \$ *Ln* 561.40 X
 \$ *Ln* 680.90 X
 \$ *CM* 401.40 ✓
 \$ *R* 5,263.60 X
 \$ *Ln* 24.80 X
 \$ *Ln* 125.40 X
 \$ *B* 1,677.20 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2301-**SHD189Z**

1 BOOT BADGE 'RENAULT'	\$	<i>nc</i>	82.40	—
1 BOOT BADGE	\$	<i>na</i>	95.80	—
1 BOOT REFLECTOR LAMP RH	\$	<i>cm</i>	277.70	✓
1 BUMPER REFLECTOR RH	\$	<i>cm</i>	16.60	✓
1 BOOT HINGE LH	\$	<i>n</i>	254.20	X
1 BOOT HINGE RH	\$	<i>n</i>	254.20	X
1 BOOT STRUT LH	\$	<i>pu</i>	145.10	X
1 BOOT STRUT RH	\$	<i>pu</i>	145.10	X
1 BOOT LOCK LINKAGE	\$	<i>pu</i>	20.60	X
1 BOOT LOCK LINKAGE HOLDER	\$	<i>pu</i>	99.50	X
1 BOOT LOCK	\$	<i>n</i>	246.60	X
1 BOOT LOCK CATCH	\$	<i>n</i>	41.70	X
1 BOOT FINISHER	\$	<i>pu</i>	344.70	X
1 BUMPER COVER FRT	\$	<i>n</i>	747.20	X
1 BUMPER ABSORBER FRT	\$	<i>pu</i>	394.68	X
1 RADIATOR GRILLE	\$	<i>nc</i>	969.90	✓
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>nc</i>	225.36	✓
1 RADIATOR GRILLE FRAME	\$	<i>pu</i>	686.00	X
1 FRAME FULL SUPPORT PANEL	\$	<i>pu</i>	592.70	X
	\$		23,358.65	
10%	\$		2,335.86	
	\$		21,022.78	

Specical Nett

1SET BUMPER CLIP FRT	\$	<i>na</i>	95.00	✓
1 FRONT NUMBER PLATE WITH MOULDING	\$	<i>pu</i>	200.00	X
1 END PANEL TRIM CLIP	\$	<i>na</i>	65.00	X
1SET PARKING AID	\$	<i>short</i>	700.00	400.00
1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	—
1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	<i>pu</i>	200.00	X
1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	—
1 EXHAUST MOUNTING REAR	\$	<i>na</i>	17.82	X
1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i>	80.00	30.00

Trans-cab Auto Services Pte Ltd**AAD2301-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD189Z

1	REAR BOOT STICKER '6555-3333'	\$	<i>na</i>	80.00	<i>30sn</i>
2	WINDSCREEN SEALANT	\$	<i>na</i>	150.00	<i>40sn</i>
1	WINDSCREEN MOULDING	\$	<i>na</i>	200.00	<i>X</i>
1	WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	130.00	<i>X</i>
TOTAL		\$		1,302.82	
TOTAL PARTS		\$		22,325.60	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>1100L</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>1200L</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>90L</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>60L</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>60L</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>60L</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	<i>120L</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD2301-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD189ZTo Check Electrical Lighting Concerned. \$ 170.00 *201***TOTAL \$ 7,580.00****Over All Total \$ 50,928.38****(LUMP SUM)****Repair Days***16 DAYS*
*8 days***LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: