

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23001199/UPA3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900024010
Claimant Vehicle No :	GBF6613L	Insured Vehicle No :	SMJ4375K
Date of Loss:	19/01/2023	Nature of Claim:	TP
		Claim No:	1352136933SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF6613L	Engine No:	HR16075463D
Make & Model:	NISSAN NV200, 1.6 DX (A)	Chassis No:	VM20100790
Reg. Date:	01/02/2017 (Man. Year: 2016)	Odometer:	168902 km
Colour:	White		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,746.40	4,446.31	1,300.09	22.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	2,230.00	910.00	28.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,886.40	6,676.31	2,210.09	24.87
Approved Total (Overridden) (S\$)		5,300.00		
(S\$)	8,886.40	5,300.00	3,586.40	40.36
+ GST 8.00/8.00% (S\$)	710.91	424.00	286.91	40.36
Nett Amount (S\$)	9,597.31	5,724.00	3,873.31	40.36
+ Car Rental (8.0 x S\$100.00/day + 8.00% GST) (S\$)		864.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,590.00		

INSPECTION

Date of Assignment:	06/02/2023	
Date Inspected:	06/02/2023	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,991.00 FN	*1,978.40 FN
2	1		*TAILGATE LOGO EMBLEM	Necessary	94.00 FN	*79.90 FN
3	1		*TAILGATE NV200 EMBLEM	Necessary	94.00 FN	*94.00 FN
4	1		*TAILGATE VENETTE EMBLEM	Necessary	94.00 FN	*68.00 FN
5	1		*TAILGATE WEATHERSTRIP	Twisted	128.00 FN	*128.00 FN
6	1		*TAILGATE LOCK	Dented / Jammed	328.00 FN	*260.60 FN
7	1		*TAILGATE INNER TRIM BOARD	Torn	248.00 FN	*248.00 FN
8	10		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FN	*- FN
9	1		*REAR BUMPER	Distorted	585.00 FN	*585.00 FN
10	2		*REAR BUMPER SIDE RETAINER	Not Necessary	120.00 FN	*- FN
11	1		*REAR BUMPER SPONGE	Torn	185.00 FN	*185.00 FN
12	1		*REAR END PANEL	Badly Dented	265.00 FN	*265.00 FN
13	1		*REAR END PANEL GARNISH	Twisted	104.00 FN	*104.00 FN
14	1		*O/S TAILLAMP	Not Necessary	280.00 FN	*- FN
15	1		*SET TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
16	1		*BTL TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
17	1		*TAILGATE GLASS INNER SEAL	Necessary	20.00 FS	*20.00 FS
18	1		*70KM/H STICKER	Necessary	30.00 FS	*10.00 FS
19	1		*5 PAX STICKER	Necessary	30.00 FS	*10.00 FS
20	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
21	1		*TAILGATE COMPANY STICKER	Necessary	500.00 FS	*500.00 FS
22	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
23	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
24	10		*REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
25	1		*O/S REAR FENDER COMPANY STICKER	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,206.00	4,845.90
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	459.60	399.59
Total Parts (\$\$)	5,746.40	4,446.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT SYSTEM AND WIRING	New	50.00	20.00
2	TRANSFER TAILGATE GLASS	New	150.00	120.00
3	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
4	RE-SPRAY ANTI-RUST	New	150.00	60.00
5	APPLY BODY SEALANT TO CAR JOINTS	New	150.00	0.00
6	INSTALL REVERSE SENSOR	New	100.00	40.00
7	TO REMOVE INNER TRIM,GARNISH AND ETC TO FACILITATE REPAIRS AND TO FIX BACK	New	120.00	0.00
8	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL ,REPAIR INNER PANEL ,REWELD INNER PANEL ,REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	1,300.00	1,080.00
9	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	1,000.00	850.00
Gross Labour Cost (\$\$)			3,140.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >