

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



		AUTOMOBILE INSI	LCII	ON KLFOKI		
INCC	ME INSURANCE	LTD	Ref:	NS/INC23001201/Nqp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	06-03-2023		
			Code:	INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLU 4976E	Veh. lı	nspected	SHA 5276M	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1210240-001	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	01/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2015	
	Chassis No.	KMHLB41UMGU080538	Colou	r	BLUE	
	Odometer	-	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST	LAKE	5 mm	
	L/H Front Tyre	205/60 R16	WEST	LAKE	5 mm	
	R/H Rear Tyre	205/60 R16	WEST	LAKE	5 mm	
	L/H Rear Tyre	205/60 R16	WEST	LAKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND O/S BODY PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/01/2023	Inspec	ction Date	01/02/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					
	•					