

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III23001211/UYA3Q2**Date:** 19/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0005332
Claimant Vehicle No : SMY2672L **Insured Vehicle No :** SNF5719E
 Date of Loss: 05/02/2023 Nature of Claim: TP Claim No: MFL2023D0001443

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY2672L**
 Make & Model: TOYOTA NOAH, 1.8 (A) Engine No: 2ZR0F25163
 Reg. Date: 25/02/2021 (Man. Year: 2020) Chassis No: ZWR800433001
 Colour: Silver Odometer: 86001 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	742.50	539.00	203.50	27.41
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,430.00	860.00	570.00	39.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,183.50	1,410.00	773.50	35.42
+ GST 8.00/8.00% (S\$)	174.68	112.80	61.88	35.42
Nett Amount (S\$)	2,358.18	1,522.80	835.38	35.42
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		1,789.55		

INSPECTION

Date of Assignment: 06/02/2023 Present Location: SME Motor Pte Ltd (Kaki Bukit)
 Date Inspected: 21/02/2023 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY2672L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR CORNER BUMPER LH (WCP)	Repair	130.00 F	*- F
2	1		*REAR BUMPER (WCP)	Distorted	360.00 F	*360.00 F
3	1		*REAR BUMPER RETAINER LH (WCP)	Bent	105.00 F	*105.00 F
4	10		*REAR BUMPER CLIPS (WCP)	Necessary	25.00 F	*25.00 F
5	1		*REAR BUMPER REFLECTOR LH (WCP)	Not Necessary	55.00 F	*- F
						F=Franchise part.
					Sub Total (\$\$)	675.00 490.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	67.50 49.00
					Total Parts (\$\$)	742.50 539.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	20.00	20.00
2	REMOVE & REFIX REAR SENSOR	New	60.00	40.00
3	LABOUR CHARGE	New	650.00	300.00
4	SPRAY PAINTING	New	700.00	500.00
Gross Labour Cost (\$\$)			1,430.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >