

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001217/TWP3Q2**Date:** 17/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00199142200
Claimant Vehicle No :	FBS5494B	Insured Vehicle No :	SCR2770S
Date of Loss:	28/01/2023	Nature of Claim: TP	Claim No: SNM23D200742/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBS5494B	Engine No:	G3P4E0001186
Make & Model:	YAMAHA AEROX 155A, 155cc	Chassis No:	MH3SG6420LJ001185
Reg. Date:	27/05/2021 (Man. Year: 2020)	Odometer:	30221 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R14	Rear Tyre Size:	140/70 R14
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,616.50	3,000.00	1,616.50	35.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	700.00	990.00	58.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,306.50	3,700.00	2,606.50	41.33
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	6,306.50	2,950.00	3,356.50	53.22
+ GST 8.00/8.00% (S\$)	504.52	236.00	268.52	53.22
Nett Amount (S\$)	6,811.02	3,186.00	3,625.02	53.22

INSPECTION

Date of Assignment:	06/02/2023		
Date Inspected:	07/02/2023	Inspected At:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD Singapore 218216
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 May 2023)	
Parts:	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS5494B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Cut	105.00 FL	*105.00 FL
2	1		*FRONT RIGHT FORK ASSY	Bent	480.00 FL	*330.00 FL
3	1		*FRONT LEFT FORK ASSY	Bent	480.00 FL	*330.00 FL
4	1		*STEERING STEM STAY	Bent	210.00 FL	*140.00 FL
5	2		*BEARINGS	Necessary	90.00 FL	*90.00 FL
6	1		*HANDLE BAR	Bent	145.00 FL	*120.00 FL
7	1		*BRAKE LEVER	Cut	55.00 FL	*55.00 FL
8	1		*RIGHT FAIRING ASSY	Cut	165.00 FL	*165.00 FL
9	2		*AMBLEMS	Necessary	50.00 FL	*50.00 FL
10	2		*FAIRING LABELS	Necessary	70.00 FL	*70.00 FL
11	1		*HEADLAMP ASSY	Cracked	395.00 FL	*395.00 FL
12	1		*LEFT FAIRING ASSY	Cut	165.00 FL	*165.00 FL
13	1		*CENTER INNER COVER	Not Necessary	155.00 FL	*- FL
14	1		*FRONT RIGHT UPPER FAIRING	Cut	175.00 FL	*175.00 FL
15	1		*RIGHT FAIRING SMALLER	Cut	75.00 FL	*75.00 FL
16	1		*MIRROR	Cracked	45.00 FL	*45.00 FL
17	1		*RIGHT BALANCER	Cut	45.00 FL	*45.00 FL
18	1		*FLOOR STEP RIGHT	Cut	145.00 FL	*145.00 FL
19	1		*CAMERA	Not Necessary	185.00 FL	*- FL
20	1		*RADIATOR COVER	Cut	75.00 FL	*75.00 FL
21	1		*EXHAUST HEAT SHIELD	Cut	105.00 FL	*105.00 FL
22	1		*EXHAUST ASSY	Bent	485.00 FL	*350.00 FL
23	1		*FLOOR STEP LOWER	Cut	105.00 FL	*105.00 FL
24	1		*FRONT SPORT RIM	Not Necessary	450.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
26	1		*RADIATOR	Not Necessary	205.00 FL	*- FL
27	1		*FRONT LOWER COVER	Deformed	125.00 FL	*125.00 FL
28	1		*FRONT BRAKE DISK	Not Necessary	115.00 FL	*- FL
29	1		*FRONT WHEEL AXLE	Bent	85.00 FL	*40.00 FL
30	1		*RADIATOR COOLANR	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,070.00	3,330.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	453.50	330.00
Total Parts (\$\$)	4,616.50	3,000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	80.00
2	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGED PARTS ,CHECK WIRING AND LIGHTING SYSTEM	New	500.00	300.00
3	SPRAY PAINTING	New	350.00	200.00
4	TO REMOVE/REFIT ,REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORKS	New	150.00	120.00
5	TO REMOVE /REFIT ,REPLACE (IF DAMAGE) CHECK AND BALANCE FRONT SPORT RIMS	New	90.00	0.00
6	BODY ALIGNMENT	New	350.00	0.00
7	LABOUR	New	150.00	0.00
Gross Labour Cost (\$\$)			1,690.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >