



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4406G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	REAR TAILLAMP L/R @\$312.40 (CONSISTENT)	CRACKED	624.80	448.20
2	REAR TAILLAMP PANEL L/R @\$292.10 (CONSISTENT)	BENT	584.20	517.40
	LESS 10% DISCOUNT		-120.90	-96.56
			1,088.10	869.04
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR REVERSE SENSOR (SN) (CONSISTENT)	DENTED	250.00	200.00
1	SET REAR CARRIER NO PLATE (SN) (CONSISTENT)	MISSING	35.00	35.00
1	REAR STEP BAR (SN) (CONSISTENT)	BENT	350.00	350.00
			635.00	585.00
<u>LABOUR</u>				
	TO REFIX /RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.(NPA)	NOT NECESSARY	-	-
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT .		1,000.00	450.00
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT .		1,000.00	500.00
			2,000.00	950.00
GRAND TOTAL			3,723.10	2,404.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CC4/HSB23001218/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.