3/23/23, 1:03 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI23001219/UQP3Q2

23/03/2023 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00138302201

**Claimant Vehicle** 

SMJ8606T

Insured Vehicle XE6832R

No:

No:

Claim

Date of Loss:

30/01/2023

Nature of Claim: TP

No:

SNM23D200923/C02/TANKL

Yes

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMJ8606T Reg No:

Make & Model: HONDA FIT, 1.3 (A) Engine No: L13B1445581 Reg. Date: 22/03/2019 (Man. Year: 2018) Chassis No: GK31338069 Colour: Yellow Odometer: 62927 km

**Engine Capacity:** 1317 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

**Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes No

**CONDITION OF TYRES** 

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15 Rear Left Side: Front Left Side: Kumho 6 mm Kumho 6 mm Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,141.44	1,559.92	581.52	27.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,110.00	590.00	34.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,841.44	2,669.92	1,171.52	30.50
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	3,841.44	2,100.00	1,741.44	45.33
+ GST 8.00/8.00% (S\$)	307.32	168.00	139.32	45.33
Nett Amount (S\$)	4,148.76	2,268.00	1,880.76	45.33

**INSPECTION** 

Date of Assignment: 06/02/2023

Hock Wah Motor Workshop Pte Ltd (Bedok)

Blk 3011, Bedok Industrial Park E,, #01-Date Inspected: 07/03/2023 Inspected At:

2008/2010/2012

Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

Reference

3/23/23, 1:03 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2023)

Parts: 144 HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMJ8606T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Badly Dented	848.30 FL	*848.30 FL
2	1		*FRONT DOOR HINGE TOP RH	Not Necessary	42.00 FL	*- FL
3	1		*FRONT DOOR HINGE BOTTOM RH	Not Necessary	42.00 FL	*- FL
4	1		*FRONT DOOR INNER LOCK RH	Damaged	268.50 FL	*268.50 FL
5	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	351.50 FL	*- FL
6	1		*FRONT DOOR OUTER KEY LOCK RH	Not Necessary	98.50 FL	*- FL
7	1		*FRONT FENDER RH	Dented / Bent	509.40 FL	*414.00 FL
8	1		*FRONT DOOR GLASS REGULATOR WITH MOTOR RH	Bent / Jammed	416.50 FL	*319.00 FL
9	1		*FRONT DOOR TOP STICKER RH	Necessary	41.00 FL	*41.00 FL
10	1		*FRONT DOOR MOULDING RH	Bent	59.10 FL	*59.10 FL
11	1		*REAR DOOR RH (NPA)	Repair	0.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.	,		
				Sub Total (S\$)	2,676.80	1,949.90
			- List Item Discount on L Item	ns 20.00/20.00% (S\$)	535.36	389.98
				Total Parts (S\$)	2,141.44	1,559.92
				8		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
<u>Lab</u>	our Items						
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	300.00			
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	750.00			
3	ANTI-RUST COATING	New	100.00	60.00			
		Gross Labour Cost (S\$)	1,700.00	1,110.00			
Report was unsubmitted during this print-out.							

< END OF ESTIMATES >