

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23001220/UQY3Q2**Date:** 27/03/2023**REFERENCE**

Insured/Claimant:	TOH HUI HUI	Policy No:	SP2001501665-01	
Date of Loss:	01/02/2023	Nature of Claim:	OD	Claim No: 202332005014

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3336E		
Make & Model:	MAZDA CX-30, 2.0 (A)	Engine No:	PE31654966
Reg. Date:	19/04/2021 (Man. Year: 2021)	Chassis No:	JM6DM2W7AM0103218
Colour:	White	Odometer:	23233 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,933.85	4,631.55	302.30	6.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,220.00	1,480.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,633.85	6,851.55	1,782.30	20.64
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	8,033.85	6,251.55	1,782.30	22.18
+ GST 8.00/8.00% (\$\$)	642.71	500.12	142.59	22.19
Nett Amount (\$\$)	8,676.56	6,751.67	1,924.89	22.18

INSPECTION

Date of Assignment:	06/02/2023		
Date Inspected:	07/02/2023	Inspected At:	Eurokars Services Pte Ltd (ubi) (HQ) 5 UBI CLOSE Singapore 408605
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts:	M1-SUV	MAZDA CX-30 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3336E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	994.32 F	*994.32 F
2	1		*RETAINER RH FRONT	Bent	24.03 F	*24.03 F
3	1		*RETAINER LH FRONT	Bent	24.03 F	*24.03 F
4	1		*RETAINER RH GRILLE TOP FRONT	Not Necessary	11.13 F	*- F
5	1		*RETAINER LH GRILLE TOP FRONT	Not Necessary	11.13 F	*- F
6	2		*GROMMET SCREW	Necessary	9.28 F	*9.28 F
7	1		*FRONT REINFORCEMENT	Bent	621.53 F	*621.53 F
8	1		*PLATE SEAL RH FRONT BUMPER	Necessary	42.91 F	*42.91 F
9	1		*PLATE SEAL LH FRONT BUMPER	Necessary	42.91 F	*42.91 F
10	1		*MESH FRONT BUMPER LOWER	Torn	102.83 F	*102.83 F
11	1		*PLATE SEAL RH MESH BUMPER LOWER	Not Necessary	30.01 F	*- F
12	1		*PLATE SEAL LH MESH BUMPER LOWER	Not Necessary	30.01 F	*- F
13	1		*HOLDER LICENSE PLATE FRONT	Deformed	97.61 F	*97.61 F
14	10		*NUT CLIP	Necessary	23.60 F	*23.60 F
15	4		*FASTENER	Necessary	9.44 F	*9.44 F
16	1		*FRONT GRILLE RADIATOR	Cracked	642.35 F	*642.35 F
17	1		*CHROME MOULD RH FRONT	Cracked	341.95 F	*341.95 F
18	1		*CHROME MOULD LH FRONT	Cracked	341.95 F	*341.95 F
19	1		*CLIP	Necessary	9.28 F	*9.28 F
20	1		*BRACKET MASCOT FRONT	Not Necessary	101.40 F	*- F
21	1		*MASCOT FRONT	Cracked	67.18 F	*67.18 F
22	2		*CLIP	Not Necessary	9.28 F	*- F
23	1		*FRONT GRILLE RAD TOP	Deformed	712.56 F	*712.56 F
24	16		*RIVET	Necessary	118.72 F	*118.72 F
25	5		*FASTENER	Necessary	15.60 F	*15.60 F
26	1		*FRONT WHEEL ARCH RH	Not Necessary	29.67 F	*- F
27	1		*FRONT WHEEL ARCH LH	Not Necessary	29.67 F	*- F
28	1		*LABEL CAUTION	Necessary	2.36 F	*2.36 F
29	1		*LABEL CAUTION	Necessary	2.36 F	*2.36 F
30	1		*FRONT NUMBER PLATE WITH CASING	Bent	70.00 FS	*70.00 FS
31	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
32	1		*SET PLATE	Broken	160.57 F	*160.57 F
33	1		*BRACKET RH,BUMPER LOWER	Cracked	59.26 F	*59.26 F
34	1		*GUIDE AIR	Torn	80.08 F	*80.08 F
35	4		*GROMMET	Necessary	14.84 F	*14.84 F
Total Parts (S\$)						4,933.85 4,631.55

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AND REPAIR FRONT FENDER RH	New	1,500.00	660.00
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH	New	1,400.00	1,260.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	180.00
5	TO CARRY -OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHouc)	New	250.00	0.00
Gross Labour Cost (\$\$)			3,700.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >