

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001222/UQP3E2**Date:** 17/03/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00065052202	
Claimant Vehicle No :	SDE737J	Insured Vehicle No :	GBJ5913G	
Date of Loss:	18/01/2023	Nature of Claim:	TP	Claim No: SNM23D200782/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDE737J		Engine No:	L13A4091006
Make & Model:	HONDA FIT, 1.3 (A)		Chassis No:	GE61083251
Reg. Date:	10/07/2009 (Man. Year: 2008)		Odometer:	174504 km
Colour:	Black			
Engine Capacity:	1339 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,211.40	7,574.64	11,636.76	60.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	2,610.00	1,240.00	32.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,061.40	10,184.64	12,876.76	55.84
Approved Total (Overridden) (\$\$)		8,000.00		
Nett Amount (\$\$)	23,061.40	8,000.00	15,061.40	65.31

INSPECTION

Date of Assignment:	06/02/2023	
Date Inspected:	06/02/2023	Inspected At: 2ND Auto Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre Singapore 417808
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2023)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDE737J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	980.00 FL	*581.20 FL
2	2		*FRONT BUMPER SIDE RETAINERS	Distorted	112.00 FL	*60.00 FL
3	1		*FRONT BUMPER TOW COVER	Not Necessary	72.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Twisted	172.00 FL	*94.20 FL
5	1		*FRONT BUMPER LOWER COVER	Not Necessary	128.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Distorted	582.00 FL	*242.60 FL
7	1		*BONNET	Buckled	1,145.00 FL	*680.20 FL
8	1		*BONNET INNER LOCK	Bent	198.00 FL	*145.00 FL
9	1		*BONNET LOCK CATCH	No such part	48.00 FL	*- FL
10	2		*BONNET HINGES	Bent	144.00 FL	*144.00 FL
11	1		*BONNET INSULATOR	Not fitted	198.00 FL	*- FL
12	1		*BONNET STAND	Not Necessary	52.00 FL	*- FL
13	2		*BONNET RUBBER STOPPER	Not Necessary	24.00 FL	*- FL
14	1		*BONNET RUBBER BEADING	Not Necessary	92.00 FL	*- FL
15	1		*LHS FRONT FENDER	Buckled	798.00 FL	*455.20 FL
16	1		*LHS FRONT FENDER INNER SPLASH SHIELD	Torn	121.00 FL	*121.00 FL
17	1		*RHS FRONT FENDER	Repair	798.00 FL	*- FL
18	1		*RHS FRONT FENDER INNER SPLASH SHIELD	Not Necessary	121.00 FL	*- FL
19	2		*RHS & LHS FENDER SIGNAL LAMP (NPA)	Not Necessary	0.00 FL	*- FL
20	2		*RHS & LHS HEADLAMP	Cracked	1,784.00 FL	*1,360.00 FL
21	2		*RHS & LHS HEADLAMP LOWER BRACKET	Cracked	224.00 FL	*116.00 FL
22	1		*FRONT CENTRE RADIATOR GRILLE	Distorted	328.00 FL	*182.00 FL
23	1		*FRONT CENTRE RADIATOR GRILLE BADGE	Missing	72.00 FL	*45.00 FL
24	1		*FRONT SUPPORT PANEL	Bent	580.00 FL	*472.60 FL
25	1		*RADIATOR	Bent / Punctured	650.00 FL	*650.00 FL
26	1		*RADIATOR SPARE TANK	Deformed	120.00 FL	*86.50 FL
27	1		*RADIATOR FAN MOTOR	Jammed	180.00 FL	*180.00 FL
28	1		*AIR CON CONDENSOR	Bent	750.00 FL	*750.00 FL
29	1		*AIR CON CONDENSOR PIPE	Bent	110.00 FL	*110.00 FL
30	1		*AIR CON CONDENSOR PIPE TO VALVE	Not Necessary	180.00 FL	*- FL
31	1		*FRONT ENGINE INTAKE MANIFOLD (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*FRONT ENGINE (NPA)	Not Necessary	0.00 FL	*- FL
33	2		*FRONT ENGINE MOUNTING (NPA)	Not Necessary	0.00 FL	*- FL
34	2		*RHS & LHS FRONT CHASSIS EXTENSION	Repair	1,344.00 FL	*- FL
35	2		*HORNS	Cracked	150.00 FL	*150.00 FL
36	1		*LHS SIDE VIEW MIRROR	Not Necessary	568.00 FL	*- FL
37	1		*FRONT WINDSCREEN	Not Necessary	980.00 FL	*- FL
38	1		*FRONT WINDSCREEN MOULDING	Not Necessary	158.00 FL	*- FL
39	1		*FRONT WIPER WASHER TANK	Deformed	172.00 FL	*105.30 FL
40	1		*FRONT WIPER GARNISH	Not Necessary	200.00 FL	*- FL
41	2		*RHS & LHS FRONT SHOCK ABSORBER	Not Necessary	656.00 FL	*- FL
42	1		*LHS FRONT LOWER ARM	Not Necessary	298.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*LHS FRONT KNUCKLE ARM	Not Necessary	272.00 FL	*- FL
44	1		*LHS FRONT TIE ROD	Not Necessary	112.00 FL	*- FL
45	1		*FRONT DRIVER (STEERING) AIRBAG	Activated	980.00 FL	*980.00 FL
46	1		*FRONT PASSENGER AIRBAG	Activated	1,100.00 FL	*1,100.00 FL
47	1		*AIRBAG SENSOR	Activated	580.00 FL	*495.00 FL
48	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
49	1		*FRONT LICENCE PLATE W/HOLDER	Bent	75.00 FS	*40.00 FS
50	1		*RADIATOR COOLANT	Necessary	60.00 FS	*30.00 FS
51	1		*SET FRONT FENDER SHIELD CLIPS	Necessary	120.00 FS	*30.00 FS
52	2		*RHS & LHS FRONT SPORTS RIM	Not Necessary	1,560.00 FS	*- FS
53	1		*FRONT DASHBOARD	Not Necessary	950.00 FS	*- FS
54	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
55	2		*RHS & LHS SPORTS RIM	Not Necessary	1,560.00 FS	*- FS
56	1		*SET BONNET INSULATOR CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,878.00	9,435.80
- List Item Discount on L Items 20.00/20.00% (\$)	3,666.60	1,861.16
Total Parts (\$)	19,211.40	7,574.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	1,600.00	1,200.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	980.00
3	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND FOCUS HEADLAMP BEAM	New	180.00	30.00
4	TO REMOVE AND REPLACE RADIATOR, PRESSURE TEST AND REFILL COOLANT }	New	120.00	100.00
5	TO REMOVE AND REPLACE AIR CON CONDENSOR, VACUUM AND REFILL GAS }	New	150.00	0.00
6	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	200.00	0.00
7	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	120.00	0.00
8	TO CARRY OUT FRONT COMPUTERISED WHEEL ALIGNMENT TEST	New	100.00	0.00
9	TO REMOVE AND REPLACE AIRBAGS AND SENSORS	New	200.00	200.00
10	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	100.00
Gross Labour Cost (\$\$)			3,850.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >