

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CC3/AIS23001223/RWY3Q2**Date:** 25/04/2023**REFERENCE**

|                   |                    |                  |              |
|-------------------|--------------------|------------------|--------------|
| Insured/Claimant: | OH CHIA-AN, MARCUS | Policy No:       | SP2003081622 |
| Date of Loss:     | 03/02/2023         | Nature of Claim: | OD           |
|                   |                    | Claim No:        | 202332005083 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMP8273M</b>                   |             |                   |
| Make & Model:               | VOLKSWAGEN GOLF, 1.4 (A7) TSI (A) | Engine No:  | CZCC06899         |
| Reg. Date:                  | 17/10/2019 (Man. Year: 2019)      | Chassis No: | WVWZZZAUZKW218482 |
| Colour:                     | Blue                              | Odometer:   | 33487 km          |
| Engine Capacity:            | 1395 cc                           |             |                   |
| Market Value/New Car Price: | S\$94,000.00                      |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/45 R17   | Rear Tyre Size:  | 225/45 R17   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                | 10,998.29         | 10,176.04         | 822.25            | 7.48          |
| Miscellaneous Items                  | 0.00              | 0.00              | 0.00              |               |
| Labour                               | 8,670.00          | 6,195.00          | 2,475.00          | 28.55         |
| Paintwork Labour                     | 0.00              | 0.00              | 0.00              |               |
| Towing                               | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b> | <b>19,668.29</b>  | <b>16,371.04</b>  | <b>3,297.25</b>   | <b>16.76</b>  |
| <b>- Excess (\$\$)</b>               | 600.00            | 600.00            | 0.00              | 0.00          |
| <b>(\$\$)</b>                        | 19,068.29         | 15,771.04         | 3,297.25          | 17.29         |
| <b>+ GST 8.00/8.00% (\$\$)</b>       | 1,525.46          | 1,261.68          | 263.78            | 17.29         |
| <b>Nett Amount (\$\$)</b>            | <b>20,593.75</b>  | <b>17,032.72</b>  | <b>3,561.03</b>   | <b>17.29</b>  |

**INSPECTION**

|                             |            |                                                                                                   |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 06/02/2023 |                                                                                                   |
| Date Inspected:             | 06/02/2023 | Inspected At: Volkswagen Group Singapore Pte Ltd (tuas) (HQ)<br>17 Tuas Ave 9<br>Singapore 639197 |
| Estimated Period of Repair: | 10.0 days  |                                                                                                   |

**Adjuster:** MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 24 Apr 2023)                      |
| <b>Parts:</b>        | 144                                                                                                                                                                          | VOLKSWAGEN GOLF 1.4 (A7) TSI (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMP8273M)                                                                                                                                    |                                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                    |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *COVER FOR BUMPER PRIMED                       | Deformed      | 1,045.57 FS | *1,045.57 FS |
| 2   | 1   |          | *SENSOR BRACKET                                | Necessary     | 11.15 FS    | *11.15 FS    |
| 3   | 1   |          | *SENSOR BRACKET                                | Necessary     | 11.15 FS    | *11.15 FS    |
| 4   | 2   |          | *SENSOR BRACKET                                | Necessary     | 21.38 FS    | *21.38 FS    |
| 5   | 1   |          | *2K-PLASTIC ADHESIVE                           | Necessary     | 60.94 FS    | *60.94 FS    |
| 6   | 1   |          | *BONDING AGENT FOR PLASTIC                     | Necessary     | 53.55 FS    | *53.55 FS    |
| 7   | 1   |          | *GUIDE PIECE BUMPER SIDE BRACKER LH            | Not Necessary | 26.73 FS    | *- FS        |
| 8   | 1   |          | *LED HEADLIGHT LH                              | Scratched     | 2,074.48 FS | *2,074.48 FS |
| 9   | 1   |          | *FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING | Not Necessary | 15.83 FS    | *- FS        |
| 10  | 1   |          | *FENDER LH                                     | Bent          | 489.47 FS   | *489.47 FS   |
| 11  | 1   |          | *CROSS SUPPORT LHS FENDER BRACKET              | Necessary     | 31.69 FS    | *31.69 FS    |
| 12  | 1   |          | *WHEELHOUSE LINER LHS FENDER LINER (LOWER)     | Not Necessary | 92.64 FS    | *- FS        |
| 13  | 1   |          | *WHEELHOUSE LINER LHS FENDER LINER (UPPER)     | Not Necessary | 148.84 FS   | *- FS        |
| 14  | 1   |          | *REAR VIEW MIRROR HOUSING                      | Scratched     | 531.75 FS   | *531.75 FS   |
| 15  | 1   |          | *MIRROR CAP PRIMED                             | Repair        | 135.73 FS   | *- FS        |
| 16  | 1   |          | *MIRROR GLASS                                  | Not Necessary | 150.13 FS   | *- FS        |
| 17  | 1   |          | *DOOR LHS FRT DOOR                             | Necessary     | 1,840.49 FS | *1,840.49 FS |
| 18  | 1   |          | *DOOR SEAL                                     | Necessary     | 95.05 FS    | *95.05 FS    |
| 19  | 1   |          | *ALU-LAMIN INSULATION DOOR INSULATOR           | Necessary     | 31.44 FS    | *31.44 FS    |
| 20  | 1   |          | *DOOR HINGE DOOR HINGE (UPPER)                 | Not Necessary | 92.56 FS    | *- FS        |
| 21  | 1   |          | *DOOR HINGE DOOR HINGE (LOWER)                 | Not Necessary | 92.56 FS    | *- FS        |
| 22  | 2   |          | *BOLT WITH POLYGON SOCKET                      | Necessary     | 8.22 FS     | *8.22 FS     |
| 23  | 1   |          | *HEX BOLT WITH INTERNAL TO<br>(4 PCS)          | Necessary     | 11.89 FS    | *11.89 FS    |
| 24  | 1   |          | *WOOFER LHS FOR DOOR SPEAKER                   | Not Necessary | 67.23 FS    | *- FS        |
| 25  | 1   |          | *POP-RIVET<br>(8 PCS)                          | Necessary     | 3.51 FS     | *3.51 FS     |
| 26  | 1   |          | *FILL HD SCREW<br>(2 PCS)                      | Necessary     | 4.49 FS     | *4.49 FS     |
| 27  | 1   |          | *FELT STRIP                                    | Necessary     | 17.40 FS    | *17.40 FS    |
| 28  | 1   |          | *CLIP<br>(6 PCS)                               | Necessary     | 7.65 FS     | *7.65 FS     |
| 29  | 1   |          | *SECTIONAL PART-PILLAR A/B                     | Bent          | 1,206.09 FS | *1,206.09 FS |
| 30  | 1   |          | *2K-INSERT FOAM                                | Necessary     | 127.21 FS   | *127.21 FS   |
| 31  | 1   |          | *SEALANT CAN BE SPRAYED                        | Necessary     | 52.88 FS    | *52.88 FS    |
| 32  | 1   |          | *ZINC SPRAY                                    | Necessary     | 54.58 FS    | *54.58 FS    |
| 33  | 1   |          | *2K-BODY ADHESIVE                              | Necessary     | 366.65 FS   | *366.65 FS   |
| 34  | 1   |          | *UNDERSEAL                                     | Necessary     | 11.16 FS    | *11.16 FS    |
| 35  | 1   |          | *SET SILL PANEL MOULDING SCUFF PLATE INNER     | Necessary     | 145.90 FS   | *145.90 FS   |
| 36  | 1   |          | *ALLOY WHEEL                                   | Scratched     | 1,857.43 FS | *1,857.43 FS |
| 37  | 1   |          | *RUBBER VALVE                                  | Necessary     | 2.87 FS     | *2.87 FS     |

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **10,998.29**    **10,176.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                             | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                         |          |                 |                 |
| 1                               | LABOUR                                  | New      | 3,360.00        | 2,240.00        |
| 2                               | SPRAY PAINT                             | New      | 3,180.00        | 2,385.00        |
| 3                               | TRANSFER DOOR MECHANISM                 | New      | 560.00          | 280.00          |
| 4                               | R&R FRT INTERIOR CARPPET                | New      | 560.00          | 280.00          |
| 5                               | B&P CHECK SHORT CIRCUIT/ HARNESS REPAIR | New      | 200.00          | 200.00          |
| 6                               | B&P DIAGNOSIS AND PROGRAMMING           | New      | 360.00          | 360.00          |
| 7                               | TO ALIGN LED HEADLIGHT                  | New      | 100.00          | 100.00          |
| 8                               | B&P WHEEL ALIGNMENT                     | New      | 300.00          | 300.00          |
| 9                               | R&R RIM & BALANCE                       | New      | 50.00           | 50.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                         |          | <b>8,670.00</b> | <b>6,195.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >