

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23001224/RWY3M4**Date:** 18/04/2023**REFERENCE**

Insured/Claimant:	LIM IMM CHOO	Policy No:	SP2000682318	
Date of Loss:	02/02/2023	Nature of Claim:	OD	Claim No: 202332005081

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ9683B		
Make & Model:	VOLKSWAGEN PASSAT, 1.8 B8 1.8 TFSI AT 3G24JZ (A)	Engine No:	CJS302619
Reg. Date:	12/12/2019 (Man. Year: 2019)	Chassis No:	WVWZZZ3CZKE057726
Colour:	Blue	Odometer:	50183 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$122,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,634.57	11,910.69	1,723.88	12.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,540.00	6,450.00	1,090.00	14.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,174.57	18,360.69	2,813.88	13.29
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	20,074.57	17,260.69	2,813.88	14.02
+ GST 8.00/8.00% (S\$)	1,605.97	1,380.86	225.11	14.02
Nett Amount (S\$)	21,680.54	18,641.55	3,038.99	14.02

INSPECTION

Date of Assignment: 06/02/2023

Date Inspected: 06/02/2023 Inspected At:

VOLKSWAGEN GROUP SINGAPORE PTE LTD
NO 17 TUAS AVE 9
SINGAPORE 639197

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2023)
Parts:	143	VOLKSWAGEN PASSAT 1.8 B8 1.8 TFSI AT 3G24JZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ9683B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Buckled	1,308.25 FS	*1,308.25 FS
2	1		*FLAP HINGE LH	Bent	103.41 FS	*103.41 FS
3	1		*HINGE COVER LH	Not Necessary	8.47 FS	*- FS
4	1		*FLAP HINGE RH	Bent	103.41 FS	*103.41 FS
5	1		*HINGE COVER RH	Not Necessary	8.47 FS	*- FS
6	1		*DECKLID WEATHERSTRIP BONNET SEAL RH	Necessary	30.49 FS	*30.49 FS
7	1		*LOCKING CATCH BONNET LATCH	Bent	72.53 FS	*72.53 FS
8	1		*HOOD LATCH BONNET LOCK	Bent	167.17 FS	*167.17 FS
9	1		*CABLE HOOD LATCH LOCK CABLE	Not Necessary	36.92 FS	*- FS
10	2		*HEXAGON SOCKET OVAL HEAD	Necessary	4.18 FS	*4.18 FS
11	1		*HOOD SILENCER BONNET INSULATOR	Deformed	203.11 FS	*203.11 FS
12	1		*COVER FOR PLENUM CHAMBER WIPER COWLING RH	Not Necessary	100.17 FS	*- FS
13	1		*COVER FOR BUMPER PRIMED	Torn	1,380.97 FS	*1,380.97 FS
14	1		*SPOILER SATIN BLACK	Not Necessary	261.88 FS	*- FS
15	1		*IMPACT BEAM REINFORCEMENT	Bent	741.78 FS	*741.78 FS
16	1		*CROSS MEMBER	Bent	178.33 FS	*178.33 FS
17	2		*POP-RIVET	Necessary	3.60 FS	*3.60 FS
18	1		*FOAM INSERT	Cracked	102.33 FS	*102.33 FS
19	1		*GUIDE PIECE BUMPER CTR BRACKET	Cracked	71.04 FS	*71.04 FS
20	1		*GUIDE PIECE BUMPER INNER BRACKET RH	Cracked	40.69 FS	*40.69 FS
21	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Necessary	44.31 FS	*44.31 FS
22	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	43.91 FS	*- FS
23	1		*SET SENSOR BRACKETS	Necessary	38.40 FS	*38.40 FS
24	1		*SENSOR PRIMED	Scratched	140.13 FS	*140.13 FS
25	1		*SEAL RING SATIN BLACK	Necessary	1.10 FS	*1.10 FS
26	1		*2K-PLASTIC ADHESIVE	Necessary	60.94 FS	*60.94 FS
27	1		*BONDING AGENT FOR PLASTIC	Necessary	53.55 FS	*53.55 FS
28	1		*HARNESS FOR BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	324.21 FS	*- FS
29	1		*PRESSURE CYLINDER WITH JE NOZZLE CYLINDER RH	Cracked	110.80 FS	*110.80 FS
30	1		*CAP PRIMED NOZZLE COVER RH	Missing	24.96 FS	*24.96 FS
31	1		*SCHLAUCHLEITUNG SCHEIN WE NOZZLE PIPE	Not Necessary	19.30 FS	*- FS
32	1		*RADIATOR GRILLE SATIN BLA	Cracked	495.16 FS	*495.16 FS
33	1		*VW SIGN BLACK/BRIGHT CHRO	Not Necessary	76.84 FS	*- FS
34	1		*VENT GRILLE WITH TRIM STR BUMPER CTR LOWER GRILLE	Cracked	189.63 FS	*189.63 FS
35	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER MLDG CHROM CTR	Scratched	186.95 FS	*186.95 FS
36	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER MLDG CHROM RH	Scratched	85.66 FS	*85.66 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*COOLING AIR GRILL SATIN B RHS FOG LAMP GRILLE	Missing	107.15 FS	*107.15 FS
38	1		*COVER STRIP SATIN BLACK RHS FOG LAMP GRILLE LOWER TRIM	Scratched	58.82 FS	*58.82 FS
39	2		*TAPPING SCREW FILL. HD.	Necessary	1.90 FS	*1.90 FS
40	1		*LED HEADLIGHT	Broken	2,257.42 FS	*2,257.42 FS
41	1		*ADJUSTMENT PART H/LAMP ADJUSTMENT	Cracked	6.25 FS	*6.25 FS
42	1		*TRIM COVER H/LAMP TOP CHROM	Missing	31.79 FS	*31.79 FS
43	1		*REPAIR KIT	Scratched	11.58 FS	*11.58 FS
44	1		*GASKET	Necessary	9.69 FS	*9.69 FS
45	1		*POWER MODULE FOR MAIN LIG	Scratched	372.35 FS	*372.35 FS
46	1		*POWER MODULE FOR LED HEAD	Cracked	260.96 FS	*260.96 FS
47	1		*POWER MODULE FOR DAY DRIV	Not Necessary	368.03 FS	*- FS
48	1		*LED LAMP	Not Necessary	277.76 FS	*- FS
49	1		*ROUND HD. SCREW 2PIECES	Necessary	4.05 FS	*4.05 FS
50	1		*SPACER	Necessary	24.36 FS	*24.36 FS
51	1		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING 2PIECES	Cracked	31.67 FS	*31.67 FS
52	1		*HALOGEN FOG LIGHTS WITH S	Broken	289.31 FS	*289.31 FS
53	1		*SPEED NUT	Necessary	1.11 FS	*1.11 FS
54	1		*HEXAGON SOCKET HEAD PANEL	Necessary	0.95 FS	*0.95 FS
55	1		*LOCK CARRIER WITH MOUNTIN	Cracked	1,127.86 FS	*1,127.86 FS
56	1		*SUPPORT FOR LOCK CARRIER	Not Necessary	29.40 FS	*- FS
57	1		*CROSS SUPPORT H/LAMP TOP PANEL RH	Bent	33.43 FS	*33.43 FS
58	1		*SEAL RING	Necessary	5.58 FS	*5.58 FS
59	1		*SEAL RING	Necessary	5.93 FS	*5.93 FS
60	1		*OIL FOR REFRIGERANT COMPR A/C OIL 0.1PIECES	Necessary	28.42 FS	*28.42 FS
61	2		*COOLANT 1B	Necessary	36.20 FS	*36.20 FS
62	1		*AIR DUCT AIR GUIDE RH	Deformed	23.31 FS	*23.31 FS
63	1		*HORN	Cracked	103.81 FS	*103.81 FS
64	1		*HALTER FUER SIGNALHORN HORN BRACKET	Not Necessary	5.98 FS	*- FS
65	1		*FLAT CONNECTOR HOUSING WI HORN WIRE HOUSING	Not Necessary	10.68 FS	*- FS
66	1		*FENDER RH	Buckled	599.25 FS	*599.25 FS
67	1		*BRACKET RHS FENDER BRACKET	Bent	55.35 FS	*55.35 FS
68	1		*DEFORMATION ELEMENT FENDER TOP BRACKET (FRT)	Bent	20.30 FS	*20.30 FS
69	1		*WHEELHOUSE LINER FENDER LINER (UPPER)	Deformed	170.06 FS	*170.06 FS
70	1		*WHEELHOUSE LINER RHS FENDER LINER (LOWER)	Deformed	129.46 FS	*129.46 FS
71	1		*EXPANDING NUT 8PIECES	Necessary	15.21 FS	*15.21 FS
72	8		*HEXAGON SOCKET HEAD PANEL	Necessary	7.60 FS	*7.60 FS
73	1		*COVER PRIMED RHS FENDER LOWER COVER	Not Necessary	46.19 FS	*- FS
74	1		*COVER STRIP CHROME RHS FENDER LOWER MLDG CHROM	Not Necessary	52.52 FS	*- FS
75	1		*LOCK CABLE INNER	Cut	107.86 FS	*77.66 FS
76	1		*RHS FENDER ELEMENT	Deformed	81.97 FS	*59.02 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **13,634.57** **11,910.69**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	B&P LEAKED CHECK,VACUUM & REGAS	New	280.00	280.00
4	A/C GAS	New	60.00	60.00
5	TO ALIGN LED HEADLIGHT	New	100.00	100.00
6	LABOUR	New	3,360.00	2,800.00
7	SPRAY PAINT	New	3,180.00	2,650.00
Gross Labour Cost (S\$)			7,540.00	6,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >