

ASS. REC. BY:

REF:

C72 / 23001226/kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 71k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10-12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNR 85756Yr Regn: 05.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttlec.c. 1496Colour: M.P. white

A/C: Insured / Std / NI / NA

Sp. Reading: 165325

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK8

1202051

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRIm / STD AJRIm or

Tyre Size: F: 185/65R15R: Goform

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 10/12/22D.O.I. 26/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 EM not ready

28/4 / 1 Rm @ 88501 Carhu

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,

SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128

Business Regn No: 269436/00J

NOT Withheld
11 Sep @ 8850h
Returning After Paint
10 days

24 JANUARY 2023

China Taiping Insurance (Singapore) PL
105 Cecil Street
#18-00 The Octagon
Singapore 069534

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SLH3750P

Accident involving vehicle no: SMR8575G/SLH3750P

DOA: 10/12/2022 at JUNCTION OF BUKIT PANJANG ROAD AND PENDING ROAD

Dear officer in charge

Estimate cost of repair for vehicle no: SMR8575G

To supplied:

Description	Qty	Amount
Front bonet	1	920.80
Front bonet hinge	2	81.00
Front bonet lock	1	135.00
Front bumper	1	1,050.60
Front bumper retainer	2	40.00
Front bumper side bracket	2	81.00
Front bumper enforcement	1	397.00
Front bumper tow cover	1	35.00
Front grille H logo	1	48.30
Front support panel	1	651.70
Front top panel bracket	1	85.00
Bumper clip	10	39.00
Foglamp cover	2	230.00
Headlamp	2	2,200.00
Headlamp chrome	2	181.60
Headlamp lower bracket	2	87.60
Front grille	1	301.90
Front grille center chrome	1	362.50
Front fender	1	509.60
Front fender inner panel	1	319.00
Front fender cowling	1	125.00
Cowling clip	10	39.00
Wiper tank	1	75.00
Radiator	1	1,350.00
Condenser	1	704.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Fan motor	<i>nn</i> 1	301.80
Fan cowling	<i>nn</i> 1	89.30
Fan blade	<i>nn</i> 2	121.00
Seatbelt	<i>nn</i> 2	607.50
Airbag ECU	<i>nn</i> 1	981.00
Dashboard airbag LH	<i>Burn</i> 1	2,336.80
Dashboard airbag RH	<i>nn</i> 1	1,605.00
Parts		16,092.50
Parts less 20%		12,874.00

1. Wheel alignment
2. Front number plate
3. Towing fee
4. To remove/replace radiator, aircon condenser, fan assembly,
And recharge aircon gas
5. To remove and replace dashboard, seatbelt, airbag assy
And all related connectors, To reprogram the airbag ECU system
6. To remove damaged parts and attachments of front portion
Repair/reshape dented areas
To straighten front chassis frames where necessary
To replace/realign all parts into same position
7. To spray paint

<i>nn</i>	60.00	X
<i>nn</i>	25.00	<i>nn</i>
	100.00	<i>nn</i>
<i>nn</i>	280.00	X
	250.00	<i>nn</i>
	900.00	<i>600</i>
	1,300.00	<i>900</i>
	15,789.00	