

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123001231/AVY3Q2**Date:** 02/05/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMF8019J **Insured Vehicle No :** GBJ1656A

Date of Loss: 11/01/2023 Nature of Claim: TP Claim No: CDMCG23000168

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF8019J**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: P520547181

Reg. Date: 26/11/2018 (Man. Year: 2018) Chassis No: JM6BN22A8K0249059

Colour: Grey Odometer: 108804 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,871.76	2,908.24	2,963.52	50.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,330.00	1,720.00	56.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,921.76	4,238.24	4,683.52	52.50
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	8,921.76	3,400.00	5,521.76	61.89
+ GST 8.00/8.00% (S\$)	713.74	272.00	441.74	61.89
Nett Amount (S\$)	9,635.50	3,672.00	5,963.50	61.89

INSPECTION

Date of Assignment: 03/02/2023

Date Inspected: 27/03/2023 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 May 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF8019J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,028.60 FL	*1,028.60 FL
2	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	72.20 FL	*72.20 FL
3	2		*REAR BUMPER SIDE REFLECTOR -LH & RH	Not Necessary	115.00 FL	*- FL
4	1		*REAR BUMPER TOW COVER	Deformed	38.10 FL	*38.10 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	498.40 FL	*498.40 FL
6	1		*REAR END PANEL	Repair	586.20 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	214.20 FL	*214.20 FL
8	2		*TAILLAMP -LH & RH	Not Necessary	1,734.40 FL	*- FL
9	1		*BOOTLID	Dented	1,066.20 FL	*1,066.20 FL
10	1		*BOOTLID LOCK	Damaged	225.20 FL	*225.20 FL
11	1		*BOOTLID WEATHERSTRIPE	Not Necessary	135.60 FL	*- FL
12	2		*BOOTLID REFLECTOR -LH & RH	Not Necessary	590.00 FL	*- FL
13	1		*MAZDA LOGO	Necessary	56.90 FL	*56.90 FL
14	1		*MAZDA 3 WORDING	Necessary	59.40 FL	*59.40 FL
15	1		*SKYACTIV EMBLEM	Necessary	63.60 FL	*63.60 FL
16	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	368.20 FL	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
18	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
19	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
20	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,242.20	3,572.80
- List Item Discount on L Items 20.00/20.00% (S\$)	1,370.44	664.56
Total Parts (S\$)	5,871.76	2,908.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	500.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	600.00
3	TO CHECK WIRING SYSTEM	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO REMOVE UPHOLSTERY	New	150.00	30.00
6	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
7	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (S\$)			3,050.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >