

Vehicle Damage Assessment Report for [SMP1166K]

Estimate Created: 07/06/2023 15:52 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 22/06/2023 15:21 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number	CDMPG23000185
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Audi	Model	A3
Engine Type			
License Plate Number	SMP1166K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$28,454.90 WITH 8 WORKING DAYS

Insurlogic 4 (22/06/2023 15:18)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
RH front bumper closing element		1	336.50	0.00 %	336.50
RH front bumper guide section		1	45.40	0.00 %	45.40
Front bumper reinforcement beam		1	974.00	0.00 %	974.00
RH horn low tone		1	224.50	0.00 %	224.50
RH front fender		1	1012.00	0.00 %	1,012.00
RH front fender rivets		5	4.00	0.00 %	20.00
Front fender bracket - RH center		1	56.10	0.00 %	56.10
Front fender brace		1	114.00	0.00 %	114.00
Front fender bracket - RH rear		1	37.50	0.00 %	37.50
Front wheel housing liner - RH		1	197.50	0.00 %	197.50
Bonnet		1	3412.00	0.00 %	3,412.00
Bonnet edge protector		1	32.80	0.00 %	32.80
RH headlamp		1	6232.00	0.00 %	6,232.00
Headlamp power module RH		1	875.50	0.00 %	875.50
Headlight heat sink - RH		1	868.00	0.00 %	868.00
Headlight control unit		1	643.00	0.00 %	643.00
Headlight hose - RH		1	47.90	0.00 %	47.90
Lift cylinder - RH		1	164.50	0.00 %	164.50
Lift cylinder hose		1	80.80	0.00 %	80.80
Lock carrier		1	853.50	0.00 %	853.50
Ready-mix coolant		1	325.20	0.00 %	325.20
radiator air guide - RH		1	30.40	0.00 %	30.40
Front aluminium rin rubber valve - RH		1	3.80	0.00 %	3.80

Parts Subtotal 16,586.90

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front bumper assy		1.0	800.00	0.00 %	800.00
Sundries		1.0	56.00	0.00 %	56.00

Materials Subtotal 856.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
To remove, check and transfer front wire harness for headlights, horns, outside temperature sensor and etc.	RnR	360.00	0.00 %	360.00
To remove and transfer RHS headlight's control unit and power module.	RnR	350.00	0.00 %	350.00
To remove and renew aircon condenser, additional radiator and check electrical fans and control unit,	RnR	1400.00	0.00 %	1,400.00
To remove and reinstall RHS front door panel trim. To remove and reinstall RHS wing mirror assy to facilitate repair.	RnR	280.00	0.00 %	280.00
Panel beating	RnR	4550.00	0.00 %	4,550.00
Wheel alignment	RnR	280.00	0.00 %	280.00
To carry out diagnostic check.	RnR	192.00	0.00 %	192.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Front fender end plate - RH	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	3600.00	0.00 %	3,600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 7,412.00

Paint Labor Subtotal 3,600.00

Labor Subtotal 11,012.00

Summary

Repair Cost 28,454.90

Discount(0 %) (0.00)

28,454.90

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 28,454.90