

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580**Our File No:** CS/III23001236/KNY3E2**Date:** 04/08/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 22/01/2023

Nature of Claim: OD

Claim No: MFL2023D0000789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE3622S**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX587166
 Reg. Date: 19/07/2016 (Man. Year: 2016) Chassis No: MR053REH104554966
 Colour: Metallic Dark Grey Odometer: 101981 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: S\$57,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Davanti 5 mm Rear Left Side: Davanti 4 mm
 Front Right Side: Davanti 5 mm Rear Right Side: Davanti 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,110.82	6,892.95	3,217.87	31.83
Miscellaneous Items	161.00	161.00	0.00	0.00
Labour	3,530.00	2,530.00	1,000.00	28.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,801.82	9,583.95	4,217.87	30.56
Approved Total (Overridden) (S\$)		7,650.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	13,801.82	6,900.00	6,901.82	50.01
+ GST 8.00/8.00% (S\$)	1,104.14	552.00	552.14	50.01
Nett Amount (S\$)	14,905.96	7,452.00	7,453.96	50.01

INSPECTION

Date of Assignment: 06/02/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 06/02/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE3622S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	639.80 FL	*639.80 FL
2	1		*FRONT CHROME GRILLE	Cracked	770.80 FL	*643.10 FL
3	1		*FRONT LOWER GRILLE	Serviceable	94.40 FL	*- FL
4	1		*LH HEADLAMP	Mtg Cracked	885.80 FL	*885.80 FL
5	1		*RH HEADLAMP	Mtg Cracked	885.80 FL	*885.80 FL
6	1		*FRONT BUMPER LH RETAIER	Distorted	102.60 FL	*102.60 FL
7	1		*FRONT BUMPER RH RETAINER	Distorted	102.60 FL	*102.60 FL
8	1		*FRONT SUPPORT PANEL	Repair	1,364.00 FL	*- FL
9	1		*FRONT BONNET	Bent	107.60 FL	*107.60 FL
10	1		*FRONT BONNET LOCK	Repair	162.20 FL	*- FL
11	1		*REAR BOORLID	Bent	947.10 FL	*947.10 FL
12	1		*REAR BOOTLID LH HINGE	Repair	83.90 FL	*- FL
13	1		*REAR BOOTLID RH HINGE	Repair	83.90 FL	*- FL
14	1		*REAR BOOTLID INSULATOR	Serviceable	437.30 FL	*- FL
15	1		*REAR BOOT WHEATHERSTRIP	Serviceable	211.10 FL	*- FL
16	1		*REAR BOOTLID LOCK	Dented	480.20 FL	*409.10 FL
17	1		*REAR BOOTLID CHROME MOULDING	Serviceable	292.50 FL	*- FL
18	1		*REAR BOOTLID TOYOTA EMBLEM	Necessary	79.70 FL	*79.70 FL
19	1		*REAR BOOT LID COROLLA EMBLEM	Necessary	81.50 FL	*81.50 FL
20	1		*REAR VOOTLID ALTIS EMBLEM	Necessary	91.60 FL	*91.60 FL
21	1		*REAR BOOTLID LH LAMP	Cracked	244.60 FL	*244.60 FL
22	1		*REAR BOOTLID RH LAMP	Cracked	244.60 FL	*244.60 FL
23	1		*LH TAILLAMP	Cracked	456.10 FL	*394.50 FL
24	1		*RH TAILLAMP	Cracked	456.10 FL	*394.50 FL
25	1		*LH TAILLAMP CLIP	Necessary	6.50 FL	*6.50 FL
26	1		*RH TAILLAMP CLIP	Necessary	6.50 FL	*6.50 FL
27	1		*LH TAILLAMP BRACKET	Serviceable	72.80 FL	*- FL
28	1		*RH TAILLAMP BRACKET	Serviceable	72.80 FL	*- FL
29	1		*REAR BUMPER	Bent	669.10 FL	*669.10 FL
30	1		*REAR BUMPER LH REFLECTOR	Serviceable	72.70 FL	*- FL
31	1		*REAR BUMPER RH REFLECTOR	Serviceable	72.70 FL	*- FL
32	1		*REAR BUMPER LH RETAINER	Distorted	131.80 FL	*131.80 FL
33	1		*REAR BUMPER RH RETAINER	Distorted	131.80 FL	*131.80 FL
34	1		*REAR LH FENDER INNER TRIM	Serviceable	396.40 FL	*- FL
35	1		*REAR RH FENDER INNER TRIM	Serviceable	396.40 FL	*- FL
36	1		*REAR END PANEL	Bent	808.00 FL	*808.00 FL
37	1		*REAR END PANEL GARNISH	Distorted	290.40 FL	*290.40 FL
Supplementary #1						
38	1		*REAR REINFORCEMENT	Bent	480.20 FL	*408.20 FL
39	1		*SPARE TYRE TOP BOARD	Cracked	390.40 FL	*292.00 FL
40	1		*REAR BUMPER LOWER BRACKET RH	Cracked	131.80 FL	*131.80 FL
41	1		*FRT NUMBER PLATE WITH CASING	Bent	45.00 FL	*45.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					13,481.10	9,175.60
- List Item Discount on L Items 25.00/25.00% (S\$)					3,370.28	2,282.65
Total Parts (S\$)					10,110.82	6,892.95
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
2	1	REAR BOOTLID CLIPS (NECESSARY)	50.00	50.00
3	1	RER BUMPER CLIPS (NECESSARY)	50.00	50.00
4	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			161.00	161.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit Front damage parts.	New	600.00	400.00
2	To putty & respray on Front damage parts.	New	600.00	400.00
3	To knock & straighten on accident area, to remove & refit Rear damage parts.	New	1,200.00	800.00
4	To putty & respray on Rear damage parts.	New	1,000.00	800.00
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	New	80.00	80.00
6	To check wiring, focus headlamp & install reverse sensor.	New	50.00	50.00
Gross Labour Cost (\$\$)			3,530.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >