

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 9791Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT O/S FENDER	DENTED	652.00	428.00
1	FRONT O/S FENDER CHROME GARNISH	NECESSARY	59.00	59.00
1	FRONT O/S FENDER TOP GARNISH	NOT NECESSARY	38.00	-
6	FRONT O/S FENDER INNER GARNISH CLIPS @\$4.50	NOT NECESSARY	27.00	-
1	FRONT O/S DOOR	DENTED / BENT	1,247.00	899.00
2	FRONT O/S DOOR TOP & LOW HINGE @\$56.00	NOT NECESSARY	112.00	-
1	FRONT O/S DOOR WEATHERSTRIP	NOT NECESSARY	149.00	-
16	FRONT O/S DOOR INNER TRIM BOARD CLIPS @\$6.00	NOT NECESSARY	96.00	-
1	FRONT O/S DOOR SIDE MIRROR CASING	NOT NECESSARY	434.00	-
1	FRONT O/S DOOR PILLAR PANEL	NOT NECESSARY	900.00	-
	LESS 10% DISCOUNT		-371.40	-138.60
			3,342.60	1,247.40
	<u>LABOUR</u>			
	TO REMOVE & REFIX FRONT O/S DOOR BOARD, DOOR GLASS, REGULATOR, MOTOR, INNER LOCK, CHANNEL, WEATHERSTRIP & NECESSARY PARTS.		200.00	60.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.		80.00	60.00
	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING.	NOT NECESSARY	120.00	-
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT O/S DOOR PILLAR PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS.		850.00	300.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		1,200.00	450.00
	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM.		50.00	20.00
			2,500.00	890.00
	GRAND TOTAL		5,842.60	2,137.40

Report Ref No. CS/UOI23001238/Uny3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/UOI23001238/Uny3e2

CHUA KANG SENG

Licensed Appraiser