

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123001239/AQY3M4**Date:** 16/03/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SLA6512C **Insured Vehicle No :** SMA2664L

Date of Loss: 28/01/2023 Nature of Claim: TP Claim No: CDMPG23000236-002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA6512C**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4926417

Reg. Date: 16/09/2009 (Man. Year: 2009) Chassis No: MR053ZEE106153505

Colour: Blue Odometer: 180114 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,776.40	4,655.82	4,120.58	46.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,110.00	1,490.00	41.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,376.40	6,765.82	5,610.58	45.33
Approved Total (Overridden) (S\$)		5,400.00		
Nett Amount (S\$)	12,376.40	5,400.00	6,976.40	56.37

INSPECTION

Date of Assignment: 03/02/2023

Date Inspected: 06/02/2023 Inspected At: Sin Yu Sin Workshop (HQ)
1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA6512C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	481.60 F	*481.60 FL
2	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	34.20 F	*34.20 FL
3	1		*FRONT BUMPER LOGO	Necessary	48.90 F	*48.90 FL
4	1		*HEADLAMP RH	Cut	543.90 F	*543.90 FL
5	1		*FRONT RH FENDER	Dented	595.40 F	*595.40 FL
6	1		*FRONT RH FENDER INNER SHIELD	Deformed	168.90 F	*168.90 FL
7	1		*FRONT RH LOWER ARM	Bent	375.70 F	*375.70 FL
8	1		*FRONT RH SHOCK ABSORBER	Not Necessary	381.90 F	*- FL
9	1		*FRONT RH KNUCKLE ARM	Damaged	516.40 F	*516.40 FL
10	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	130.90 F	*130.90 FL
11	1		*FRONT RH ANTI-ROLL BAR LINKAGE	Not Necessary	96.90 F	*- FL
12	1		*FRONT RH DOOR	Dented	1,141.30 F	*1,141.30 FL
13	1		*FRONT RH DOOR LOCK	Not Necessary	321.40 F	*- FL
14	1		*FRONT RH DOOR WEATHERSTRIPE	Not Necessary	278.90 F	*- FL
15	1		*FRONT RH DOOR PROTECTOR	Necessary	131.40 F	*131.40 FL
16	1		*FRONT RH DOOR PROTECTOR CHROME MOULDING	Necessary	32.80 F	*32.80 FL
17	1		*ROCKER PANEL OUTER GARNISH	Repair	655.30 F	*- FL
18	1		*REAR RH DOOR	Dented	1,089.40 F	*1,089.40 FL
19	1		*REAR RH DOOR WEATHERSTRIPE	Not Necessary	260.90 F	*- FL
20	1		*REAR RH DOOR PROTECTOR	Necessary	139.40 F	*139.40 FL
21	1		*REAR RH DOOR PROTECTOR CHROME MOULDING	Necessary	30.90 F	*30.90 FL
22	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
23	1		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
24	1		*FRONT RH WHEEL RIM	Cut	850.00 FS	*400.00 FS
25	1		*FRONT RH TYRE	Not Necessary	280.00 FS	*- FS
26	1		*FRONT RH DOOR BLACK TAPE	Necessary	50.00 FS	*50.00 FS
27	1		*ROCKER PANEL OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
28	1		*REAR RH DOOR BLACK TAPE	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,776.40	6,021.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,365.28
Total Parts (\$\$)	8,776.40	4,655.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO TRANSFER FRONT AND REAR DOOR FITTINGS	New	300.00	160.00
6	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	180.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (S\$)			3,600.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >