

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD	Re	ef:	CS3/LPC23001242/Rvy3e2	
	300 BEACH ROAD #17-04/07 THE CC) NCOURSESINGAPORE 19955		ate:	28/02/2023	
			Co	ode:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YN 5241T	Veh. Inspected		SNG 1169M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/026926	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		06/02/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA VOXY	c.c		1986	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	ZRR700147403	Colour		BLACK	
	Odometer	258308 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	YOKOHAMA		6 mm	
	L/H Front Tyre	215/45 R17	YOKOHAMA		6 mm	
	R/H Rear Tyre	215/45 R17	YOKOHAMA		6 mm	
	L/H Rear Tyre	215/45 R17	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	01/02/2023	Inspect Date / Tim	ne	07/02/2023 (05:37 PM)	
	Survey held at	SK GARAGE				
		NO. 5 SOON LEE STREET #01-34 SINGAPORE 627607				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23001242/Rvy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DEOD Anto Computerat OAE Lineared Assessing

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$