

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123001246/RQY3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKK9795S**Insured Vehicle No :** GBH1675E

Date of Loss: 01/02/2023

Nature of Claim:

TP

Claim No: CDMCG23000277

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKK9795S**

Make & Model: ADIVA AD1 200, 190cc 3W

Engine No: CMM007466

Reg. Date: 20/09/2013 (Man. Year: 2013)

Chassis No: SCBFN63W7EC088780

Colour: Black

Odometer: 9240 km

Engine Capacity: 3993 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/40Z R20

Rear Tyre Size:

275/40Z R20

Front Left Side: Pirelli 7 mm

Rear Left Side:

Pirelli 7 mm

Front Right Side: Pirelli 7 mm

Rear Right Side:

Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	88,384.90	77,266.80	11,118.10	12.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,300.00	18,900.00	9,400.00	33.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	116,684.90	96,166.80	20,518.10	17.58
+ GST 8.00/8.00% (S\$)	9,334.79	7,693.34	1,641.45	17.58
Nett Amount (S\$)	126,019.69	103,860.14	22,159.55	17.58

INSPECTION

Date of Assignment: 06/02/2023

Date Inspected: 07/02/2023 Inspected At:

Wearnes Automotive Pte Ltd (Leng Kee 2)

45 Leng Kee Road

Singapore 159103

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$11,118.10 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Feb 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK9795S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE PANEL FRAME LH	Buckled	22,625.40 FS	*22,625.40 FS
2	1		*LH UPPER SOUND ABSOR	Necessary	87.80 FS	*87.80 FS
3	1		*LH LOWER SOUND ABSOR	Necessary	81.10 FS	*81.10 FS
4	1		*LHR SIDE WINDOW (LAM)	*Check	3,944.10 FS	*- FS
5	1		*PROT RUB STRIP DOOR	Necessary	659.90 FS	*659.90 FS
6	1		*LH TRIM STRIP FOR FE	Necessary	562.00 FS	*562.00 FS
7	1		*LH LOWER TRIM STRIP	Necessary	997.60 FS	*997.60 FS
8	1		*LH UPPER TRIM FOR DO	Necessary	1,082.70 FS	*1,082.70 FS
9	1		*QTR GLASS CHROME FIN	Necessary	1,340.40 FS	*1,340.40 FS
10	1		*DOOR LH	Bent	24,832.80 FS	*24,832.80 FS
11	1		*WIN GUIDE SEAL MARG	Necessary	2,152.10 FS	*2,152.10 FS
12	1		*LH SEAL FOR DOOR WIN	Necessary	3,421.40 FS	*3,421.40 FS
13	1		*DOOR SEAL	Necessary	450.10 FS	*450.10 FS
14	1		*LH WINDOW APERTURE S	*Check	7,174.00 FS	*- FS
15	1		*SPLASH GUARD LH	Necessary	275.90 FS	*275.90 FS
16	10		*ADHESIVE TAPE 50MM	Necessary	17.00 FS	*17.00 FS
17	1		*SEAL LH	Necessary	226.20 FS	*226.20 FS
18	1		*DIV BAR SEAL REAR QT	Necessary	369.70 FS	*369.70 FS
19	1		*SEAL LH	Necessary	424.80 FS	*424.80 FS
20	1		*SEAL GLASS GUIDE LH	Necessary	755.00 FS	*755.00 FS
21	1		*SEAL LH	Necessary	471.20 FS	*471.20 FS
22	10		*EXPANDING RIVET	Necessary	15.00 FS	*15.00 FS
23	2		*NOISE INSULATION LH	Necessary	284.60 FS	*284.60 FS
24	1		*DOOR TRIM STRIP LH	Necessary	113.40 FS	*113.40 FS
25	10		*POP RIVET	Necessary	17.00 FS	*17.00 FS
26	1		*ANTI-DRUM LAYER DOOR	Necessary	118.00 FS	*118.00 FS
27	3		*ZV0890100070/NOISE D	Necessary	1,875.30 FS	*1,875.30 FS
28	1		*SEAL SEALANT	Necessary	50.50 FS	*50.50 FS
29	4		*195ML BETAMETE 2098	Necessary	1,552.00 FS	*1,552.00 FS
30	2		*D PRIMER GLASS & P	Necessary	93.80 FS	*93.80 FS
31	4		*SEALANT WINDSCREEN	Necessary	771.60 FS	*771.60 FS
32	1		*WINDSCREEN REAR	Necessary	11,412.70 FS	*11,412.70 FS
33	1		*WINDSCREEN FILM REAR	Necessary	111.60 FS	*111.60 FS
34	1		*AIRBAG WARNING LBL E	Necessary	18.20 FS	*18.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	88,384.90	77,266.80
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE LH DOOR ,LH DOOR MLDG,SEAL LH QTR PANEL ,LH QTR GLASS	New	9,600.00	8,000.00
2	TO BLEND & SPRAY PAINT LH DOOR ,LH QTR PANEL,SIDE A PILLAR ,RR BUMPER	New	8,000.00	4,000.00
3	TO REMOVE & REPLACE RR WINDSCREEN	New	1,600.00	1,600.00
4	TO INSTALL REAR WINDSCREEN FILM	New	280.00	280.00
5	TO REMOVE AND TRANSFER LH DOOR INTERIOR COMPONENTS	New	800.00	800.00
6	TO REMOVE & REFIT LH QTR SIDE TRIM UPPER ,SIDE TRIM LOWER ,ROOF LINING ,SEAT AND TO VACUUM DRILING DEBRIS	New	7,000.00	3,200.00
7	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	1,020.00	1,020.00
Gross Labour Cost (\$\$)			28,300.00	18,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >