

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS3/INC23001247/Tqy3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	20/02/2023	
	ATTN: FIONA SHE	N		Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMR 3034J	Veh. Inspected		SJZ 1316C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1207638-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		06/02/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO EX FORTE	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	KNAFU411MA5261977	Colour		BLACK	
	Odometer	189039 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/60 R15	MICHELIN		6 mm	
	L/H Front Tyre	195/60 R15	MICHELIN		6 mm	
	R/H Rear Tyre	195/60 R15	MICHELIN		6 mm	
	L/H Rear Tyre	195/60 R15	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	HICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5.	General Information					
	Accident Date	30/01/2023	Inspect Date /	Time	06/02/2023 (10:30 AM)	
	Survey held at	GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/INC23001247/Tqy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor