



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC22011254/Tqy3e2-1	
			Date: 30/03/2023	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBJ 1328Y		Veh. Inspected	GBH 1591M
Policy No.			Coverage (\$)	0.00
Claim No.	22/22/22/VC05/026524		Excess (\$)	0.00
Assign From	HUEY NI		Assign Date	04/02/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE		c.c	2982
Engine No.	HIDDEN		Year of Reg.	2018
Chassis No.	KDH2015029547		Colour	WHITE
Odometer	119053 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre	195 R15		GRENLANDER	6 mm
L/H Front Tyre	195 R15		GRENLANDER	6 mm
R/H Rear Tyre	195 R15		GRENLANDER	6 mm
L/H Rear Tyre	195 R15		GRENLANDER	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/11/2022		Inspection Date	09/11/2022
Survey held at	37 Loyang Way Singapore 508734			
Repairer	MICHELIN ENGINEERING PTE LTD			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	