

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG23001257/APA3Q2**Date:** 05/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900141247
Claimant Vehicle No :	SMR8175C	Insured Vehicle No :	SLQ2971C
Date of Loss:	04/02/2023	Nature of Claim:	TP
		Claim No:	4291249150SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8175C		
Make & Model:	AUDI A1, 999cc SB S LINE 1.0 TFSI S TRONIC (A)	Engine No:	DKJ046042
Reg. Date:	23/01/2020 (Man. Year: 2019)	Chassis No:	WAUZZZGB8LR008840
Colour:	Yellow	Odometer:	30770 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,245.00	199.20	8,045.80	97.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,242.00	1,610.00	56.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,097.00	1,441.20	9,655.80	87.01
+ GST 8.00/8.00% (\$\$)	887.76	115.30	772.46	87.01
Nett Amount (\$\$)	11,984.76	1,556.50	10,428.26	87.01
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
Nett Liability (\$\$)		1,736.50		

INSPECTION

Date of Assignment:	28/02/2023		
Date Inspected:	28/02/2023	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,839.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	151.00 FS	*- FS
3	1		*FRONT BUMPER SPOILER -RH	Not Necessary	119.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Cut	249.00 FS	*199.20 FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	198.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE PROFILE -RH	Not Necessary	43.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	127.00 FS	*- FS
8	1		*HEADLIGHT -RH	Not Necessary	4,830.00 FS	*- FS
9	1		*LIFT CYLINDER-RH	Not Necessary	165.00 FS	*- FS
10	1		*LIFT CYLINDER HOSE	Not Necessary	71.00 FS	*- FS
11	1		*RADIATOR AIR GUIDE -RH	Not Necessary	53.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,245.00 199.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER	New	900.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,852.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >