



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2303947

INV Date 20/06/2023

Reference CC4/LPC23001269/Kpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. WWC 8399

Insured Veh. GBF 6911B

Claim No. 22/23/23/VC05/026941

Policy No. Z22VC05013439

Accident Date 06/02/2023

Inspection Date 08/02/2023

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (8%) | 32.00 |
| Grand Total | 432.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|-----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|---------------------------------------------------------------|--------------------|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | | Ref: CC4/LPC23001269/Kpa3q2 Date: 20/06/2023 Code: LPC2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBF 6911B | Veh. Inspected | WWC 8399 |
| | Policy No. | Z22VC05013439 | Coverage (\$) | 0.00 |
| | Claim No. | 22/23/23/VC05/026941 | Excess (\$) | 0.00 |
| | Assign From | GERALD | Assign Date | 07/02/2023 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA HIACE (M) | c.c | 2494 |
| | Engine No. | HIDDEN | Year of Reg. | 2012 |
| | Chassis No. | PN1HS02P204008827 | Colour | WHITE |
| | Odometer | 353696 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195 R15X8 | WEST LAKE | 9 mm |
| | L/H Front Tyre | 195 R15X8 | WEST LAKE | 9 mm |
| | R/H Rear Tyre | 195 R15X8 | WEST LAKE | 5 mm |
| | L/H Rear Tyre | 195 R15X8 | WEST LAKE | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 06/02/2023 | Inspection Date | 08/02/2023 |
| | Survey held at | TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WWC 8399

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | TAILGATE | BENT | 1,850.00 | 1,850.00 |
| 1 | TAILGATE W/SCREEN MOULDING | NOT NECESSARY | 180.00 | - |
| 1 | TAILGATE TRIM BOARD | SERVICEABLE | 322.00 | - |
| 1 | TAILGATE CENTER LOGO | NECESSARY | 68.00 | 68.00 |
| 1 | TAILGATE OUTER GARNISH | SERVICEABLE | 380.00 | - |
| 1 | TAILGATE LOCK | BENT | 465.00 | 465.00 |
| 1 | TOYOTA STICKER | TO REPAIR SEE LABOUR | 165.00 | - |
| 1 | HIACE STICKER | NECESSARY | 165.00 | 165.00 |
| 2 | TAILLAMPS | O/S MTG CRACKED | 798.00 | 399.00 |
| 2 | TAILLAMP LOWER BRACKETS | TO REPAIR SEE LABOUR | 280.00 | - |
| 2 | TAILLAMP PANELS | TO REPAIR SEE LABOUR | 480.00 | - |
| 2 | REAR SIDE PANELS (NPA) | TO REPAIR SEE LABOUR | - | - |
| 1 | REAR BUMPER | BENT | 580.00 | 580.00 |
| 2 | REAR BUMPER BRACKETS | TO REPAIR SEE LABOUR | 228.00 | - |
| 2 | REAR BUMPER SIDE STAYS | TO REPAIR SEE LABOUR | 180.00 | - |
| 1 | REAR EXHAUST | TO REPAIR SEE LABOUR | 685.00 | - |
| 1 | SPARE TYRE BRACKET | BENT | 480.00 | 376.30 |
| 1 | END PANEL | BENT | 552.00 | 552.00 |
| 1 | END PANEL TOP METAL STRIP | DENTED | 330.00 | 198.00 |
| 1 | END PANEL TOP LATCH | SERVICEABLE | 68.00 | - |
| 1 | FLOOR PANEL (NPA) | TO REPAIR SEE LABOUR | - | - |
| 4 | REAR BUMPER LOWER BRACKETS (ADDITIONAL) | MISSING | 85.00 | 85.00 |
| 2 | REAR APRON PANEL(ADDITIONAL) | TO REPAIR SEE LABOUR | 280.00 | - |
| 1 | REAR EXHAUST (NPA) (ADDITIONAL) | TO REPAIR SEE LABOUR | - | - |

Report Ref No. CC4/LPC23001269/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|---------------------------|-------------------|
| | LESS 25% DISCOUNT | | -2,155.25 | -1,184.58 |
| | | | 6,465.75 | 3,553.72 |
| 1 | TAILGATE WEATHERSTRIP (50%) (SN) | DISTORTED / DENTED | 285.00 | 142.50 |
| | LESS 25% DISCOUNT | | -71.25 | - |
| | | | 213.75 | 142.50 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 2 | T REAR W/SCREEN SEALANT (SN) | NECESSARY | 120.00 | 40.00 |
| 1 | SET REVERSE SENSOR (SN) | DENTED | 300.00 | 200.00 |
| 1 | REAR NO PLATE WITH FRAME (SN) | SERVICEABLE | 50.00 | - |
| 1 | SPARE TYRE (\$200.00) (50%) (SN) | CUT | 600.00 | 100.00 |
| 1 | REAR FLOOR PANEL TOP STEEL PLATE (SN) (ADDITIONAL) | SERVICEABLE | 600.00 | - |
| | | | 1,670.00 | 340.00 |
| | <u>LABOUR</u> | | | |
| | LABOUR CHARGES TO DO CUTTING ,WELDING REPAIR REPLACE REAR ACCIDENT AFFECTED AREA .INCLUSIVE OF THE REPAIR OF TOYOTA STICKER ,TAILLAMP LOWER BRACKETS,TAILLAMP PANELS,REAR SIDE PANELS ,REAR BUMPER BRACKETS ,REAR BUMPER SIDE STAYS,REAR EXHAUST AND FLOOR PANEL. | | 1,200.00 | 600.00 |
| | TO REMOVE REFIX REAR W/SCREEN . | | 140.00 | 120.00 |
| | TO TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE . | | 120.00 | 60.00 |
| | TO DO REAR CHASSIS BODY ALIGNMENT. | NOT NECESSARY | 350.00 | - |
| | TO DO ANTI RUST . | | 120.00 | 60.00 |
| | TO SEAL GAP ,WATERRPROOFING ON REAR CUTTING WELDING ,ACCIDENT AFFECTED AREA. | | 250.00 | 30.00 |
| | TO REPLACE REAR EXHAUST . | NOT NECESSARY | 180.00 | - |
| | TO REMOVE REFIX ,SIDE TRIM ,TRIM BOARD ,FLOOR BOARD ETC. | | 280.00 | 60.00 |
| | TO DO SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREA. | | 1,000.00 | 700.00 |

Report Ref No. CC4/LPC23001269/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------|------------------------------------------------|---------------|---------------------------|-------------------|
| | LABOUR CHARGES TO REPAIR EXHAUST .(ADDITIONAL) | NOT NECESSARY | 60.00 | - |
| | | | 3,700.00 | 1,630.00 |
| GRAND TOTAL | | | 12,049.50 | 5,666.22 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 4,300.00 |

Report Ref No. CC4/LPC23001269/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WWC 8399

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WWC 8399

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. WWC 8399

RE-INSPECTION

