

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB23001270/KPA3Q2**Date:** 24/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02

Claimant Vehicle No : SKM8873X **Insured Vehicle No :** SLQ3950G

Date of Loss: 02/02/2023 Nature of Claim: TP Claim No: MFL2023D0001810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM8873X**

Make & Model: BMW X3 XDRIVE20I, 2.0 4WD SR HID DSC NAV (A) Engine No: A5450605N20B20A

Reg. Date: 21/04/2014 (Man. Year: 2013) Chassis No: WBAWX320100B28378

Colour: White Odometer: 99238 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18

Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,536.20	7,679.31	2,856.89	27.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,370.00	1,040.00	43.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,946.20	9,049.31	3,896.89	30.10
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	12,946.20	7,200.00	5,746.20	44.39
+ GST 8.00/8.00% (S\$)	1,035.70	576.00	459.70	44.39
Nett Amount (S\$)	13,981.90	7,776.00	6,205.90	44.39
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		8,522.75		

INSPECTION

Date of Assignment: 07/02/2023

Date Inspected: 07/02/2023 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts:	M1-SUV	BMW X3 XDRIVE20I 2.0 4WD SR HID DSC NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM8873X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA (BUCKLED / CRACKED)	Not Consistent With The Impact	1,589.65 FL	*- FL
2	1		*REAR BUMPER TOWING COVER	N/S Dented	187.20 FL	*93.60 FL
3	2		*REAR BUMPER CTR PARKING SENSOR	Scratched / Missing	511.30 FL	*511.30 FL
4	1		*REAR BUMPER CENTRE PAD (CRACKED)	Not Consistent With The Impact	252.65 FL	*- FL
5	1		*REAR BUMPER CENTRE PAD GARNISH	Missing	93.40 FL	*93.40 FL
6	1		*REAR BUMPER LOWER COVER	Distorted	128.25 FL	*128.25 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	854.50 FL	*854.50 FL
8	2		*REAR BUMPER INNER PARTS	Cracked	386.40 FL	*386.40 FL
9	1		*REAR END PANEL -LOWER	Bent	631.65 FL	*631.65 FL
10	1		*REAR END PANEL -TOP	Serviceable	856.95 FL	*- FL
11	1		*TAIL GATE	Bent	2,088.95 FL	*2,088.95 FL
12	1		*REAR EXHAUST HEAT SEAL	Serviceable	155.20 FL	*- FL
13	1		*REAR EXHAUST CHROME PIPE	Dented	158.65 FL	*158.65 FL
14	1		*REAR EXHAUST MOUNTING	Serviceable	38.15 FL	*- FL
15	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
16	1		*REAR BUMPER RIVET	Necessary	30.00 FS	*30.00 FS
17	1		*REAR EXHAUST BOX	Bent	1,403.50 FL	*1,403.50 FL
18	1		*CENTRE EXHAUST PIPE	Bent	1,334.50 FL	*1,334.50 FL
19	2		*HEADREST AIR BAG	Activated	325.10 FL	*325.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,086.00	8,079.80
- List Item Discount on L Items 5.00/5.00% (\$)	549.80	400.49
Total Parts (\$)	10,536.20	7,679.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING FRONT AND REAT SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	80.00	30.00
4	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	60.00	60.00
5	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	500.00
6	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	1,000.00	600.00
Gross Labour Cost (\$\$)			2,410.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >