2/15/23, 10:46 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23001271/TVY3Q2

15/02/2023 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MR006842 **Claimant Vehicle**

SHD7160J Insured Vehicle No: SMX3297K No:

Date of Loss: 05/02/2023 Nature of Claim: TP Claim No: M2300819

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD7160J

HYUNDAI I40, 1.7 D CRDi (A) D4FDFU561541 Make & Model: Engine No:

Reg. Date: 17/11/2016 (Man. Year: 2016) Chassis No: KMHLB41UMHU096364

Colour: Blue Odometer: 862361 km

Engine Capacity: Market Value/New Car

N/A

1685 cc

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes Good Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 205/60 R16 Rear Tyre Size: Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,102.72	267.60	835.12	75.73
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	650.00	560.00	90.00	13.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) 1,763.72	838.60	925.12	52.45
Approved Total (Overridden) (S\$)	650.00		
(1	S\$) 1,763.72	650.00	1,113.72	63.15
+ GST 8.00/8.00% (S\$) 141.10	52.00	89.10	63.15
Nett Amount (S\$) 1,904.82	702.00	1,202.82	63.15

INSPECTION

07/02/2023 Present Location: Date of Assignment: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 06/02/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2023)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD7160J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	553.00 FL	*- FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER MAT	Not Necessary	50.00 F	*- F
4	1		*ADVERTISEMENT LOGO- BUMPER	Necessary	50.00 F	*50.00 F
5	1		*ADVERTISEMENT LOGO- FENDER	Necessary	200.00 F	*200.00 F
6	1		*RERA BUMPER BEAM	Not Necessary	428.40 FL	*- FL
F=Fra	nchise	part. L=ListIte	mDisc.	Sub Total (S\$)	1,303.40	272.00
			- List Item Discount o	n L Items 20.00/20.00% (S\$)	200.68	4.40
				Total Parts (S\$)	1,102.72	267.60
			Report was unsubmitted d	uring this print-out.		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		11.00	11.00
	Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			-
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
		Gross Labour Cost (S\$)	650.00	560.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >