

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI23001272/UQY3Q2**Date:** 25/04/2023**REFERENCE**

Insured/Claimant: ONG YUU KOCK Policy No: -
Date of Loss: 06/02/2023 Nature of Claim: OD Claim No: CDMPG23000296

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU6365E**
Make & Model: HONDA ODYSSEY, 2.4 (A) Engine No: K24W72041570
Reg. Date: 08/12/2017 (Man. Year: 2017) Chassis No: JHMRC1890HC204324
Colour: Silver Odometer: 108963 km
Engine Capacity: 2356 cc
Market Value/New Car Price: S\$100,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,351.74	4,656.13	4,695.61	50.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,080.00	6,040.00	3,040.00	33.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,431.74	10,696.13	7,735.61	41.97
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	17,431.74	9,696.13	7,735.61	44.38
+ GST 8.00/8.00% (S\$)	1,394.54	775.69	618.85	44.38
Nett Amount (S\$)	18,826.28	10,471.82	8,354.46	44.38

INSPECTION

Date of Assignment: 07/02/2023
Date Inspected: 07/02/2023 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU6365E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD COMP	Bent / Buckled	539.02 FS	*539.02 FS
2	1		*LABEL AIR CONDITIONER CAUTION	Necessary	1.42 FS	*1.42 FS
3	1		*LOCK ASSYHOOD	Serviceable	85.27 FS	*- FS
4	1		*HINGE COMPR HOOD	Bent	38.10 FS	*38.10 FS
5	1		*HINGE COMPL HOOD	Bent	38.10 FS	*38.10 FS
6	1		*BULKHEAD COMP FR	Bent	348.82 FS	*348.82 FS
7	1		*CONDENSER COMP	Not Necessary	547.42 FS	*- FS
8	1		*RADIATOR COMP	Not Necessary	1,081.57 FS	*- FS
9	1		*FACE ,FR.BUMPER	Dented	561.97 FS	*561.97 FS
10	1		*BASE ,MID GRILLE	Cracked	154.20 FS	*154.20 FS
11	1		*UPPER MOULDING ,MIDDLE GRILLE	Cracked	124.50 FS	*124.50 FS
12	1		*MOLDING ,MIDDLE GRILLE	Cracked	119.17 FS	*119.17 FS
13	1		*LOWER MOULDING ,R.MID GR	Cut	32.02 FS	*32.02 FS
14	1		*LOWER MOULDING ,L.MIDDLE GRILLE	Cut	32.02 FS	*32.02 FS
15	1		*BEAM COMP.FR.BUMPER	Bent	234.30 FS	*234.30 FS
16	1		*SPACERR.FR.BUMPER SIDE	Necessary	9.45 FS	*9.45 FS
17	1		*SPACERL.FR.BUMPER SIDE	Necessary	9.45 FS	*9.45 FS
18	1		*CLIP BUMPER (14 PCS)	Necessary	24.15 FS	*24.15 FS
19	1		*BASEFR .GRILLE	Serviceable	135.60 FS	*- FS
20	1		*MOLDINGFR,GRILLE	Cracked	253.65 FS	*253.65 FS
21	1		*EMBLEMFR	Necessary	23.10 FS	*23.10 FS
22	1		*NUT PUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
23	1		*HEADLIGHT ASSYR.WITH LED	Cracked	1,887.00 FS	*1,887.00 FS
24	1		*HEADLIGHT ASSYL.WITH LED	Serviceable	1,887.00 FS	*- FS
25	1		*FENDER COMPR FR	Repair	440.40 FS	*- FS
26	1		*FENDER COMPL FR	Repair	440.40 FS	*- FS
27	10		*CLIPINNER FENDER	Not Necessary	26.25 FS	*- FS
28	6		*CLIP ABUMPER	Not Necessary	11.70 FS	*- FS
29	6		*COOLANT ANTI-FREEZE TYPE 2	Necessary	104.40 FS	*104.40 FS
30	1		*NUMBER PLATE WITH CASING -S	Bent	45.00 FS	*45.00 FS
31	1		*SUNDRIES	Necessary	50.00 FS	*10.00 FS
32	1		*CLIPFR.GRILLE (4 PCS)	Necessary	7.20 FS	*7.20 FS
33	1		*BEAML.FR.BUMPER UPPER	Cracked	27.97 FS	*27.97 FS
34	1		*BEAMR.FR.BUMPER UPPER	Cracked	27.97 FS	*27.97 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	9,351.74 4,656.13
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	160.00
2	BODY JOINT SEALANT	New	100.00	100.00
3	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	New	450.00	320.00
4	REMOVE & INSTALL FR SENSORS	New	200.00	0.00
5	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	New	500.00	280.00
6	REMOVE & INSTALL RADIATOR WITH FITTINGS	New	450.00	240.00
7	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS	New	3,400.00	2,600.00
8	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,800.00	2,340.00
Gross Labour Cost (S\$)			9,080.00	6,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >