

Vehicle Damage Assessment Report for [SLU6365E]

Estimate Created: 11/04/2023 12:15 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 11/04/2023 12:57 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	OD	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Honda	Model	Odyssey
Engine Type			
License Plate Number	SLU6365E	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$10,696.13 WITH 6 WORKING
DAYS

Insurlogic 4 (11/04/2023 12:57)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Hood comp		1	718.70	-25.00 %	539.03
Label air conditioner caution		1	1.90	-25.00 %	1.43
Hood hinge RH		1	50.80	-25.00 %	38.10
Hood hinge LH		1	50.80	-25.00 %	38.10
Headlamp bulb		1	465.10	-25.00 %	348.83
Front bumper		1	749.20	-25.00 %	561.90
Front grille upper moulding middle		1	166.00	-25.00 %	124.50
Front lower grille moulding RH		1	42.70	-25.00 %	32.03
Front lower grille moulding middle LH		1	42.70	-25.00 %	32.03
Front bumper beam		1	312.40	-25.00 %	234.30
Front bumper spacer side LH		1	12.60	-25.00 %	9.45
Front bumper clips		14	2.30	-25.00 %	24.15
Front grille moulding		1	338.24	-25.00 %	253.68
Front emblem		1	30.80	-25.00 %	23.10
Push nut		2	2.10	-25.00 %	3.15
Headlamp assy RH		1	2516.00	-25.00 %	1,887.00
Anti Freeze type 2 coolant		6	23.20	-25.00 %	104.40
Front bumper side space RH		1	12.60	-25.00 %	9.45
Front grille moulding base		1	205.60	-25.00 %	154.20
Front grille molding middle		1	158.90	-25.00 %	119.18
Front grille clips		4	2.40	-25.00 %	7.20
Front bumper upper beam LH		1	37.30	-25.00 %	27.98
Front bumper upper beam RH		1	37.30	-25.00 %	27.98

Parts Subtotal 4,601.17

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Front number plate with casing		1.0	45.00	0.00 %	45.00

Materials Subtotal 45.00

LaborReplace/RnR

Description	Type	Cost	Markup/Disc %	Price
Sundries	RnR	10.00	0.00 %	10.00
Inspect front lighting mechanism & focus.	RnR	160.00	0.00 %	160.00
Body joint sealant.	RnR	100.00	0.00 %	100.00
Perform setting on multi view cameras and smart.	RnR	320.00	0.00 %	320.00
Remove and aircon condenser with fittings.	RnR	280.00	0.00 %	280.00
Remove and install radiator with fittings	RnR	240.00	0.00 %	240.00
Panel beating	RnR	2600.00	0.00 %	2,600.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
LH front fender	Medium	0.00	0.00 %	0.00
RH front fender	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	2340.00	0.00 %	2,340.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 3,710.00

Paint Labor Subtotal 2,340.00

Labor Subtotal 6,050.00

Summary

Repair Cost 10,696.17

Discount(0 %) (0.00)

10,696.17

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 10,696.17