5/2/23, 10:07 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS4/CTI23001276/KVP3M4
3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 **Date:** 02/05/2023

REFERENCE

Insured/Claimant: SANIQUO PTE LTD Policy No: DMCVSNW00053482201

Date of Loss: 05/02/2023 Nature of Claim: OD Claim No: SNM23D200948/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YQ3448L

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR1SDEP Engine No:

(CBU) (M)

Reg. Date: 22/04/2021 (Man. Year: 2021) Chassis No: FEA01BA35124

Colour: White Odometer: 0 km

Engine Capacity: 2998 cc Market Value/New Car Price: \$\$85,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75R15 Rear Tyre Size: 185/75R15 (D)
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 2/2 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		22,990.00	18,850.00	4,140.00	18.01
Miscellaneous Items		500.00	280.00	220.00	44.00
Labour		1,631.20	1,631.20	0.00	0.00
Paintwork Labour		132.64	132.64	0.00	0.00
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	25,253.84	20,893.84	4,360.00	17.26
	- Excess (S\$)	350.00	350.00	0.00	0.00
	(S\$)	24,903.84	20,543.84	4,360.00	17.51
	+ GST 8.00/8.00% (S\$)	1,992.31	1,643.51	348.80	17.51
	Nett Amount (S\$)	26,896.15	22,187.35	4,708.80	17.51

INSPECTION

Date of Assignment: 07/02/2023 Present Location: Ding Auto Pte Ltd (HQ)

DING AUTO PTE LTD

4P10E58036

Date Inspected: 07/02/2023 Inspected At: BLK 10 #01-20 SIN MING IND EST SEC C

SINGAPORE 575645

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,090.00 NETT) 5/2/23, 10:07 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 May 2023)

Parts: N/A MITSUBISHI CANTER 3.0 D FEA01BR1SDEP (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YQ3448L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*PARTS - TOTAL AMOUNT	_	22,990.00 F	*18,850.00 F
r ranomoo pare		Total Parts (S\$)	22,990.00	18,850.00
	Report was unsubm	nitted during this print-out.		

Recommended Miscellaneous Items

No Qty	Particulars		Repairer's	Amount
Miscella	neous Items			
1 1	ECU - DIAGNOSIS/RE-PROGRAMMING		500.00	280.00
		Sub Total (S\$)	500.00	280.00
1 1	ECU - DIAGNOSIS/RE-PROGRAMMING	Sub Total (S\$)		

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paii</u>	ntwork Labour			
1	Total Paint Labour	New	79.80	79.80
2	Total Paint Materials	New	52.84	52.84
Lab	our Items			
3	Total Panel/Mechanical Labour	New	1,631.20	1,631.20
		Gross Labour Cost (S\$)	1,763.84	1,763.84

< END OF ESTIMATES >

Report was unsubmitted during this print-out.