

ASS. REQ. BY:

REF: CTZ/ 230012761kv

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Soon: _____

Consistent?: Yes or No

Est. Repairs: _____

12 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / 24 NOT ready

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)

Report Format:

Lump Sum / I.B.I.: (\$)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - St _____

F - RS _____

Others _____

TOTAL _____

Report Format:
Lump Sum / I.B.I.: (\$)

Veh No: _____

YQ 3448L

Yr Regn: 04 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Mit Car cc 2998

Colour: _____

White

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng No: _____

C/N: _____

FE A018A 35124

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: MIT / S/Rim / STD A/Rim or

Tyre Size: F: _____

185/75R15

R: _____

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. _____

4 mm

R/Bal. _____

22 mm

L/Bal. _____

4 mm

L/Bal. _____

22 mm

D.O.A. 5/2/23

D.O.I. _____

7/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The lorry caught fire, the cause of fire probably

The UIC / Chassis frame / Body Structure affected due to collision.

due to short circuit of the dashboard compartment