

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001277/RWP3M4
Date: 01/03/2023**REFERENCE**

| | | | | | |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------|--------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMPCSNW00271202200 | | |
| Claimant Vehicle No : | SMJ9634E | Insured Vehicle No : | SJY2240K | | |
| Date of Loss: | 03/02/2023 | Nature of Claim: | TP | Claim No: | SNM23D200913/C02/KHONGLH |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | | | |
|-----------------------------|---------------------------------------------|-------------|-------------------|--|--|
| Reg No: | SMJ9634E | | | | |
| Make & Model: | SKODA OCTAVIA, 1.5 STYLE TSI MHEV(A) SA (A) | Engine No: | DFY077257 | | |
| Reg. Date: | 07/01/2022 (Man. Year: 2021) | Chassis No: | TMBBR7NX4MY179745 | | |
| Colour: | Black | Odometer: | 16145 km | | |
| Engine Capacity: | 1498 cc | | | | |
| Market Value/New Car Price: | N/A | | | | |
| Sum Insured (S\$): | Market Value/New Car Price | | | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/45R18 | Rear Tyre Size: | 225/45R18 |
| Front Left Side: | Goodyear 6 mm | Rear Left Side: | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 4,120.81 | 2,351.00 | 1,769.81 | 42.95 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,680.00 | 2,120.00 | 3,560.00 | 62.68 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 9,800.81 | 4,471.00 | 5,329.81 | 54.38 |
| + GST 8.00/8.00% (S\$) | 784.06 | 357.68 | 426.38 | 54.38 |
| Nett Amount (S\$) | 10,584.87 | 4,828.68 | 5,756.19 | 54.38 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|----------------------------------------------------------------------------|
| Date of Assignment: | 07/02/2023 | | |
| Date Inspected: | 08/02/2023 | Inspected At: | Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

| | |
|----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 01 Mar 2023) |
| Parts: 143 | SKODA OCTAVIA 1.5 STYLE TSI MHEV(A) SA (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMJ9634E) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|-----------------------------------------------------|---------------|--------------------------|-----------------|-----------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 1,843.66 FS | *1,843.66 FS | |
| 2 | 1 | | *UNBEKANNT (TOW COVER) | Not Necessary | 28.10 FS | *- FS | |
| 3 | 1 | | *UNBEKANNT LHR BUMPER BRACKET (SIDE) | Not Necessary | 48.60 FS | *- FS | |
| 4 | 1 | | *GUIDE PROFILE RHS RHR BUMPER BRACKET (SIDE) | Not Necessary | 48.60 FS | *- FS | |
| 5 | 1 | | *UNBEKANNT LHR BUMPER BRACKET (OUTER) | Not Necessary | 65.94 FS | *- FS | |
| 6 | 1 | | *GUIDE PROFILE RHR BUMPER BRACKET (OUTER) | Not Necessary | 65.94 FS | *- FS | |
| 7 | 1 | | *UNBEKANNT RR BUMPER BRACKET (CTR) | Not Necessary | 84.22 FS | *- FS | |
| 8 | 1 | | *UNBEKANNT REINFORCEMENT | Not Necessary | 625.49 FS | *- FS | |
| 9 | 1 | | *2K-PLASTIC ADHESIVE | Necessary | 84.64 FS | *84.64 FS | |
| 10 | 1 | | *BONDING AGENT FOR PLASTIC | Necessary | 74.37 FS | *74.37 FS | |
| 11 | 4 | | *SENSOR PRIMED | Not Necessary | 778.52 FS | *- FS | |
| 12 | 4 | | *SEAL RING SATIN BLACK | Not Necessary | 24.40 FS | *- FS | |
| 13 | 1 | | *SENSOR BRACKET | Necessary | 18.66 FS | *18.66 FS | |
| 14 | 1 | | *SENSOR BRACKET | Necessary | 18.66 FS | *18.66 FS | |
| 15 | 1 | | *SENSOR BRACKET | Necessary | 18.66 FS | *18.66 FS | |
| 16 | 1 | | *SENSOR BRACKET | Necessary | 18.66 FS | *18.66 FS | |
| 17 | 1 | | *UNBEKANNT RR BUMPER LOWER SPOILER | Scratched | 273.69 FS | *273.69 FS | |
| | | | | | Total Parts (S\$) | 4,120.81 | 2,351.00 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---------------------------------------|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | B&P CHECK SHORT CIRCUIT/HARNES REPAIR | New | 280.00 | 0.00 |
| 2 | B&P DIAGNOSIS AND PROGRAMMING | New | 480.00 | 480.00 |
| 3 | LABOUR | New | 2,520.00 | 840.00 |
| 4 | SPRAY PAINTING | New | 2,400.00 | 800.00 |
| | | | Gross Labour Cost (\$\$) | 5,680.00 |
| | | | | 2,120.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >