

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA23001283/UWY3M4**Date:** 07/03/2023**REFERENCE**

Insured/Claimant:	HENG CHIN GUAN	Policy No:	MP306018	
Date of Loss:	04/02/2023	Nature of Claim:	OD	Claim No: MPC03977/RL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF8414M		Engine No:	2ZR1831929
Make & Model:	TOYOTA WISH, 1.8 (A)		Chassis No:	JTDGG20W80J005080
Reg. Date:	13/09/2016 (Man. Year: 2016)		Odometer:	54737 km
Colour:	Grey			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	S\$58,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,432.60	9,180.60	-748.00	-8.87
Miscellaneous Items	365.00	228.00	137.00	37.53
Labour	2,210.00	1,430.00	780.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,007.60	10,838.60	169.00	1.54
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	11,007.60	10,238.60	769.00	6.99
+ GST 8.00/8.00% (\$\$)	880.61	819.09	61.52	6.99
Nett Amount (\$\$)	11,888.21	11,057.69	830.52	6.99

INSPECTION

Date of Assignment:	07/02/2023	Present Location:	SME Motor Pte Ltd (Kaki Bukit) SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883
Date Inspected:	08/02/2023	Inspected At:	
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF8414M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Deep Cut	290.00 F	*290.00 F
2	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
3	1		*FRT BUMPER UNDER COVER (WCP)	Torn	95.00 F	*95.00 F
4	1		*FRT RH SHOCK ABSORBER (WCP)	Bent	235.00 F	*235.00 F
5	1		*FRT RH SHOCK ABSORBER MOUNTING (WCP)	Twisted	105.00 F	*105.00 F
6	1		*FRT RH LOWER ARM (WCP)	Bent	195.00 F	*195.00 F
7	1		*RFT RH LOWER ARM BALL JOINT (WCP)	Bent	95.00 F	*95.00 F
8	1		*FRT RH KNUCKLE ARM (WCP)	Bent	255.00 F	*255.00 F
9	1		*FRT RH KNUCKLE BEARING (WCP)	Necessary	90.00 F	*90.00 F
10	1		*FRT RH DRIVE SHAFT (WCP)	Broken	750.00 F	*750.00 F
11	1		*ANTI ROLL BAR (WCP)	Not Necessary	235.00 F	*- F
12	1		*ANTI ROLL BAR LINK RH (WCP)	Bent	95.00 F	*95.00 F
13	1		*STEERING RACK ASSY (WCP)	Bent/Jammed	850.00 F	*850.00 F
14	1		*STEERING CROSSMEMBER (WCP)	Dented	950.00 F	*950.00 F
15	1		*CENTER CROSSMEMBER (WCP)	Bent	245.00 F	*245.00 F
16	1		*FRT ENGINE MOUNTING (WCP)	Not Necessary	165.00 F	*- F
17	1		*REAR ENGINE MOUNTING (WCP)	Not Necessary	135.00 F	*- F
18	1		*FRT ENGINE UNDER COVER (WCP)	Torn	95.00 F	*95.00 F
19	8		*ENGINE UNDER COVER CLIP (WCP)	Necessary	16.00 F	*16.00 F
20	1		*FRT RH FENDER INNER COWLING (WCP)	Torn	115.00 F	*115.00 F
21	10		*INNER COWLING CLIP (WCP)	Necessary	20.00 F	*20.00 F
22	1		*REAR RH SHOCK ABSORBER (WCP)	Bent	130.00 F	*130.00 F
23	1		*REAR RH WHEEL HUB (WCP)	Damaged	380.00 F	*380.00 F
24	1		*REAR AXLE (WCP)	Bent	950.00 F	*950.00 F
25	2		*RH SPORTS RIM SAMPLE (NPA) (WCP)	Warped	0.00 F	*1,300.00 F
Supplementary #1						
26	1		*FRONT RH WHEEL HUB (WCP)	Bent	135.00 F	*135.00 F
27	1		*FRONT RH SHOCK ABSORBER MOUNTING (WCP)	Repeated	85.00 F	*- F

Report was unsubmitted during this print-out.

3/7/23, 3:21 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*ENGINE OIL SUMP (WCP)	Dented	150.00 F	*150.00 F
29	1		*ENGINE OIL SUMP GASKET (WCP)	Necessary	55.00 F	*55.00 F
30	1		*FRONT LH LOWER ARM (WCP)	Cut/Bent	195.00 F	*195.00 F
31	1		*FRONT LH LOWER ARM BALL JOINT (WCP)	Twisted	95.00 F	*95.00 F
32	1		*FRONT RH TIE ROD END (WCP)	Bent	85.00 F	*85.00 F
33	2		*REAR AXLE BUSH (WCP)	Necessary	210.00 F	*210.00 F
<u>Supplementary #2</u>						
34	1		*FRT RH DISC ROTOR (WCP)	Warped	145.00 F	*145.00 F
F=Franchise part.						
Sub Total (\$\$)					7,666.00	8,346.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					766.60	834.60
Total Parts (\$\$)					8,432.60	9,180.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT RH TYRE (60%) Cut	280.00	168.00
2	1	RADIATOR COOLANT Not Necessary	25.00	0.00
Supplementary #1				
3	1	ENGINE OIL Necessary	60.00	60.00
Sub Total (S\$)			365.00	228.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	0.00
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH CROSSMEMBER & RACK)	New	350.00	350.00
4	REMOVE & REFIX REAR UNDERCARRIAGE (WITH AXLE)	New	350.00	300.00
5	4 WHEEL ALIGNMENT	New	80.00	60.00
6	LABOUR CHARGE	New	600.00	300.00
7	SPRAY PAINTING	New	700.00	400.00
Gross Labour Cost (S\$)			2,210.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >