

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23001284/KWP3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00000272301		
Claimant Vehicle No :	SNB9433Z	Insured Vehicle No :	SMC7406Y		
Date of Loss:	31/01/2023	Nature of Claim:	TP	Claim No:	SNM23D200794/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB9433Z	Engine No:	2ZR2L86989
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800492829
Reg. Date:	23/09/2021 (Man. Year: 2021)	Odometer:	105246 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Arivo 8 mm	Rear Left Side:	Triangle 8 mm
Front Right Side:	Arivo 8 mm	Rear Right Side:	Triangle 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,479.06	14,515.09	27,963.97	65.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,280.00	3,020.00	6,260.00	67.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	51,759.06	17,535.09	34,223.97	66.12
Approved Total (Overridden) (\$\$)		14,000.00		
(\$\$)	51,759.06	14,000.00	37,759.06	72.95
+ GST 8.00/8.00% (\$\$)	4,140.72	1,120.00	3,020.72	72.95
Nett Amount (\$\$)	55,899.78	15,120.00	40,779.78	72.95

INSPECTION

Date of Assignment:	12/02/2023	
Date Inspected:	07/02/2023	Inspected At: 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 Repairer: My Car Consultant Pte Ltd (Ubi)
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2023)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB9433Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,985.00 FL	*1,025.00 FL
2	1		*FRONT BUMPER LOWER GARNISH	Serviceable	412.00 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Cracked	298.00 FL	*298.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	598.00 FL	*598.00 FL
5	2		*FRONT BUMPER BRACKET	Repair	288.00 FL	*- FL
6	1		*FRONT GRILLE	Mtg Cracked	788.00 FL	*788.00 FL
7	1		*FRONT GRILLE LOGO WITH SENSOR	Serviceable	1,125.00 FL	*- FL
8	1		*FRONT GRILLE OUTER GARNISH	Serviceable	488.00 FL	*- FL
9	1		*HEADLAMP	N/S Mtg Cracked	7,790.00 FL	*3,665.10 FL
10	1		*FRONT HEADLAMP LOWER BRACKET	Repair	122.00 FL	*- FL
11	1		*REAR BUMPER	Bent	798.20 FL	*798.20 FL
12	2		*REAR BUMPER REFLECTOR	Serviceable	166.40 FL	*- FL
13	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	324.40 FL	*171.45 FL
14	1		*REAR BUMPER TOWING COVER	Dented	45.00 FL	*45.00 FL
15	1		*REAR BUMPER SENSOR WIRE HARNESS	Serviceable	387.00 FL	*- FL
16	1		*TAILGATE	Bent	2,110.25 FL	*1,732.10 FL
17	1		*TAILGATE INNER TRIM	Buckled	589.00 FL	*589.00 FL
18	1		*TAILGATE HYBRID SYNERGY DRIVE LOGO	Necessary	141.10 FL	*141.10 FL
19	1		*TAILGATE OUTER CHROME MOULDING C/W SENSOR	Cracked	741.00 FL	*741.00 FL
20	1		*TAILGATE WEATHERSTRIPE	Distorted / Dented	391.05 FL	*360.70 FL
21	1		*TAILGATE LOCK	Jammed	512.00 FL	*452.80 FL
22	1		*TAILGATE LOCK CATCH	Repair	42.30 FL	*- FL
23	2		*TAILGATE INNER SIDE GARNISH	Serviceable	318.00 FL	*- FL
24	1		*TAILGATE WINDSCREEN GLASS	Shattered	1,359.00 FL	*1,260.80 FL
25	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	387.00 FL	*178.10 FL
26	1		*TAILGATE DETECTOR	Serviceable	287.00 FL	*- FL
27	1		*TAILGATE BUZZER	Cracked	198.00 FL	*198.00 FL
28	1		*TAILGATE WIPER MOTOR	Serviceable	712.00 FL	*- FL
29	1		*TAILGATE WIPER ARM	Serviceable	212.00 FL	*- FL
30	1		*TAILGATE INNER CENTRE GARNISH	Mtg Cracked	321.00 FL	*321.00 FL
31	2		*TAILGATE INNER SIDE GARNISH	Mtg Distorted	424.00 FL	*424.00 FL
32	2		*TAILGATE NUMBER PLATE LAMP	Serviceable	136.00 FL	*- FL
33	1		*TAILGATE OUTER LOCK SENSOR	Serviceable	322.00 FL	*- FL
34	2		*TAILAMP	Serviceable	2,030.00 FL	*- FL
35	2		*TAILAMP LOWER PANEL (OUTER)	Repair	718.00 FL	*- FL
36	2		*TAILAMP LOWER PANEL (INNER)	Repair	624.00 FL	*- FL
37	1		*TAILAMP LOWER GARNISH	Serviceable	451.00 FL	*- FL
38	2		*REAR FENDER	Repair	3,064.00 FL	*- FL
39	2		*REAR FENDER INNER TRIM LOWER	Buckled	2,250.00 FL	*1,512.20 FL
40	2		*REAR FENDER INNER TRIM TOP	Serviceable	596.00 FL	*- FL
41	2		*REAR FENDER COWLING	Serviceable	428.00 FL	*- FL
42	1		*REAR FENDER QUARTER GLASS MOULDING RH	Serviceable	159.00 FL	*- FL
43	1		*REAR FENDER AIR VANT RH	Serviceable	68.00 FL	*- FL
44	1		*REAR AIRCON BLOWER	Serviceable	2,258.00 FL	*- FL
45	2		*SLIDING DOOR RAILING TOP GARNISH	Serviceable	996.00 FL	*- FL
46	1		*REAR END PANEL (OUTER)	Bent	689.20 FL	*689.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR END PANEL (INNER)	Repair	685.00 FL	*- FL
48	1		*REAR END PANEL TOP GARNISH	Buckled	391.45 FL	*168.20 FL
49	1		*REAR FLOOR PANEL	Repair	2,489.00 FL	*- FL
50	1		*SET REAR FLOOR PANEL TOP BOARD	Cracked	1,241.00 FL	*1,105.50 FL
51	1		*REAR FLOOR PANEL TOP TOOLS GARNISH	Serviceable	412.00 FL	*- FL
52	1		*REAR EXHAUST PIPE	Repair	1,359.00 FL	*- FL
53	1		*REAR EXHAUST PIPE HEAT SHIELD	Repair	321.00 FL	*- FL
54	2		*REAR EXHAUST MOUNTING	Serviceable	64.40 FL	*- FL
55	1		*REAR SPARE TYRE BOLT	Serviceable	32.00 FL	*- FL
56	1		*REAR BATTERY TRAY	Serviceable	214.00 FL	*- FL
57	1		*REAR BATTERY	Serviceable	450.00 FL	*- FL
58	1		*REAR SEAT ASSY RH	Cover Cracked	4,857.00 FL	*231.00 FL
59	2		*REAR CHASSIS EXTENSION	Repair	774.00 FL	*- FL
60	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*60.00 FS
61	1		*FRONT NUMBER PLATE WITH CASING	Serviceable	100.00 FS	*- FS
62	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*45.00 FS
63	1		*REAR CARRIER	Bent	600.00 FS	*600.00 FS
64	1		*REAR CAMERA	Shorted	300.00 FS	*300.00 FS
65	1		*SET TAILAMP CLIP	Necessary	30.00 FS	*30.00 FS
66	1		*REAR BUMPER REVERSE SENSOR	No such part	220.00 FS	*- FS
67	1		*REVERSE CAMERA	Serviceable	350.00 FS	*- FS
68	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
69	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
70	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
71	1		*SET TAILGATE OUTER MOULDING CLIPS	Necessary	30.00 FS	*30.00 FS
72	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
73	2		*SET REAR FENDER INNER TRIM BOARD CLIP	Necessary	100.00 FS	*100.00 FS
74	2		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
75	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
76	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
77	1		*REAR FENDER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
78	1		*REAR BATTERY	Serviceable	200.00 FS	*- FS
79	1		*SET TOOLS	Serviceable	200.00 FS	*- FS
80	1		*REAR TOP MAT	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	55,588.75	18,888.45
- List Item Discount on L Items 25.00/25.00% (\$)	13,109.69	4,373.36
Total Parts (\$)	42,479.06	14,515.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESET TROUBLE CODE	New	300.00	180.00
2	CHECK AND RESET FAULT CODE LIGHT ON HYBRID BATTERY	New	500.00	200.00
3	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
4	REMOVE AND REFIT REAR SEAT UPHOLSTERY	New	400.00	120.00
5	REMOVE AND REFIT REAR AIRCON BLOWER	New	150.00	0.00
6	REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	0.00
7	REMOVE AND REFIT REAR FENDER GLASS	New	160.00	0.00
8	REMOVE AND REFIT REAR EXHAUST SYSTEM	New	150.00	0.00
9	REMOVE AND REFIT TAILGATE MECHANISM	New	150.00	60.00
10	TO CHECK ELECTRICAL WIRING	New	200.00	40.00
11	REAR CHASSIS REALIGNMENT	New	200.00	0.00
12	PANEL BEATING ON AFFECTED AREA	New	3,400.00	1,100.00
13	SPRAY ON AFFECTED AREA	New	3,400.00	1,200.00
Gross Labour Cost (S\$)			9,280.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >