



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AJL 7600

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--------------------------|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 2 | FRONT FORK TUBE ASSY | TO REPAIR SEE LABOUR | 640.00 | - |
| 1 | FORK UNDER BRACKET | NOT NECESSARY | 185.00 | - |
| 1 | FRONT WHEEL RIM | NOT NECESSARY | 380.00 | - |
| 1 | FRONT RIM SHAFT | NOT NECESSARY | 45.00 | - |
| 1 | FRONT RIM BEARING | NOT NECESSARY | 38.00 | - |
| 1 | FRONT BRAKE DISC | NOT NECESSARY | 185.00 | - |
| 1 | HANDLE BAR | CUT / BENT | 88.00 | 88.00 |
| 1 | SET HANDLE-BAR ENDS | N/S MISSING | 74.00 | 30.00 |
| 1 | SET HAND GRIP | TORN | 55.00 | 55.00 |
| 1 | HANDLE BAR INNER BRACKET | NOT NECESSARY | 78.00 | - |
| 1 | HEADLAMP ASSY | SCRATCHED | 485.00 | 290.00 |
| 1 | SET SIDE MIRRORS | N/S CUT | 110.00 | 60.00 |
| 1 | FRONT FOOTREST BRACKET | BENT | 65.00 | 65.00 |
| 2 | FRONT FOOTREST RUBBERS | N/S TORN | 70.00 | 25.00 |
| 1 | GEAR PEDAL | BENT | 42.00 | 42.00 |
| 2 | REAR FOOTRESTS | N/S CUT | 80.00 | 40.00 |
| 2 | REAR FOOTREST BRACKETS | TO REPAIR SEE LABOUR | 156.00 | - |
| 1 | SET FAIRING ASSY | CRACKED | 525.00 | 420.00 |
| | LESS 10% DISCOUNT | | -330.10 | -111.50 |
| | | | 2,970.90 | 1,003.50 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SET NUMBER PLATE (SN) | NECESSARY | 38.00 | 20.00 |
| 2 | FORK OILS (SN) | NOT NECESSARY | 30.00 | - |
| 2 | FORK OIL SEALS (SN) | NOT NECESSARY | 56.00 | - |
| 1 | SET STEERING CONE (SN) | NOT NECESSARY | 185.00 | - |
| 1 | SET STICKER (SN) | NECESSARY | 180.00 | 60.00 |
| 1 | REAR BOX (SN) | CUT | 380.00 | 200.00 |
| 1 | REAR BOX BRACKET (SN) | BENT | 180.00 | 120.00 |
| | | | 1,049.00 | 400.00 |

Report Ref No. CS/SMR23001288/Uvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| | LABOUR | | | |
| | TO CHECK WIRING AND RESET HEADLAMP FOCUSING. | NOT NECESSARY | 80.00 | - |
| | TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FORK TUBE ASSY AND REAR FOOTREST BRACKETS. | | 480.00 | 250.00 |
| | TO RE-ALIGN BODY FRAME. | NOT NECESSARY | 420.00 | - |
| | | | 980.00 | 250.00 |
| | GRAND TOTAL | | 4,999.90 | 1,653.50 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 1,300.00 |

Report Ref No. CS/SMR23001288/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.