



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 7356P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	ABSORBER REAR @\$250.00	NOT NECESSARY	500.00	-
1	BACK REST (KAPPA) KV42A	SERVICEABLE	120.00	-
1	BASE PLATE (GIVI) BOX REAR PLASTIC	SERVICEABLE	147.00	-
1	BOX REAR (KAPPA) K-VENTURE 42L	CUT	825.00	690.00
1	COVER REAR WITH PLATE LIGHT	DISTORTED	93.29	93.29
1	EMBLEM HONDA 70MM	NECESSARY	39.00	39.00
1	HOSE OIL	NOT NECESSARY	55.00	-
1	MUDGUARD REAR	DEFORMED	95.00	95.00
1	PLATE NUMBER REAR (6.5 INCH X 9 INCH)	SCRATCHED	31.00	31.00
1	CAP PROTECTOR EXHAUST (ADDITIONAL)	DAMAGED	55.00	55.00
	LESS 10% DISCOUNT		-	-100.33
			1,960.29	902.96
	<u>LABOUR</u>			
	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.		260.00	180.00
			260.00	180.00
	GRAND TOTAL		2,220.29	1,082.96
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,082.96

Report Ref No. CS/INC23001293/Uny3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.