



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23001293/Uny3e2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 16/05/2023

ATTN: ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 2511D	Veh. Inspected	FBQ 7356P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1208433-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	07/02/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA NSS300A	c.c	279
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MLHNF0790J5000803	Colour	WHITE / BLUE
Odometer	26347 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70-15	PIRELLI	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-14	PIRELLI	7 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/02/2023	Inspect Date / Time	07/02/2023 (03:50 PM)
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------