

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN		Ref:	CS3/INC23001294/Tvy3e2	
	75 BRAS BASAH R	ROAD SINGAPORE 189557		Date:	11/04/2023
	ATTN: AZHARI			Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLC 2592L	Veh. Inspected		SNE 1888G
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1201310-002	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		07/02/2023
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ GLC250	c.c		1991
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	WDC2533092F299418	Colour		BLACK
	Odometer	92664 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	275/45 R20	MICHELIN		6 mm
	L/H Front Tyre	275/45 R20	MICHELIN		6 mm
	R/H Rear Tyre	275/45 R20	MICHELIN		6 mm
	L/H Rear Tyre	275/45 R20	MICHELIN		6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT N/S PORTION.			
5.	General Information				
	Accident Date	14/12/2022	Inspect Date / T	Time	07/02/2023 (11:15 AM)
	Survey held at	RS GARAGE SERVICES PTE LTD			
		BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC23001294/Tvy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor