

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FE 1625T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TOP COWLING	TO REPAIR SEE LABOUR	285.00	-
2	SIDE MIRRORS	O/S CUT	140.00	70.00
2	FRONT SIGNALS	NOT NECESSARY	175.00	-
1	HANDLE-BAR	NOT NECESSARY	268.00	-
1	SET HAND GRIP	NOT NECESSARY	70.00	-
2	HANDLE BAR ENDS	O/S CUT	125.00	38.00
1	BRAKE LEVER	CUT	95.00	60.00
1	FRONT FOOTREST	TO REPAIR SEE LABOUR	170.00	-
1	FRONT FOOTREST RUBBER	TORN	90.00	90.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	155.00	-
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	780.00	-
1	REAR LAMP	CRACKED	380.00	190.00
1	REAR COVER	CRACKED	520.00	300.00
1	REAR SIGNAL O/S	CRACKED	175.00	80.00
	LESS 10% DISCOUNT		-342.80	-82.80
			3,085.20	745.20
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	REAR BENT	38.00	20.00
			38.00	20.00
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF TOP COWLING, FRONT FOOTREST, BRAKE PEDAL AND EXHAUST ASSY.		480.00	250.00
			560.00	250.00
	GRAND TOTAL		3,683.20	1,015.20

Report Ref No. CS/INC23001296/Uqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	800.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. CS/INC23001296/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser