



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                   |  |   |   |            |
|---|--|---|---|------------|
| INCOME INSURANCE LTD<br>75 BRAS BASAH ROAD<br>INCOME CENTRESINGAPORE 189557<br>ATTN: CHARLOTTE CHEW |  |   | Ref: CS/INC23001296/Uqy3e2<br>Date: 18/05/2023<br>Code: INC |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |   |   |            |
|   | Insured Veh.   | GV 8338A  | Veh. Inspected  | FE 1625T   |
|   | Policy No.   |   | Coverage (\$)   | 0.00       |
|   | Claim No.  | MT/1208799-001  | Excess (\$)   | 0.00       |
|   | Assign From  | HAZALYSA BINTE IBRAHIM  | Assign Date   | 07/02/2023 |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |   |   |            |
|   | Make & Model   | YAMAHA RX11   | c.c   | 115        |
|   | Engine No.   | HIDDEN  | Year of Reg.  | 1985       |
|   | Chassis No.  | 52A001186   | Colour  | BLUE       |
|   | Odometer   | 55866 KM  | Steering  | IN ORDER   |
|   | Brakes   | IN ORDER  | Modification  | SPORTS RIM |
|   | General  | GOOD  |   |            |
| <b>3. Conditions of Tyres</b>   |  |   |   |            |
|   |  | Size  | Make  | Balance    |
|   | R/H Front Tyre   | 90-80-17  | MICHELIN  | 6 mm       |
|   | L/H Front Tyre   |   |   | mm         |
|   | R/H Rear Tyre  | 90-80-17  | BRIDGESTONE   | 6 mm       |
|   | L/H Rear Tyre  |   |   | mm         |
| <b>4. Description of Damages</b>  |  |   |   |            |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR PORTION.<br>DAMAGES SEE DETAILS.  |   |   |            |
| <b>5. General Information</b>   |  |   |   |            |
|   | Accident Date  | 20/01/2023  | Inspection Date   | 07/02/2023 |
|   | Survey held at   | EROFIA MOTOR TRADING PTE LTD<br>1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883 |   |            |
| <b>5a. Remarks</b>  |  |   |   |            |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |            |
| <b>5b. Estimate Days of Repair</b>  |  |   |   |            |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 2 Working Days  |            |